

SANTA BARBARA UNIFIED SCHOOL DISTRICT




February 6, 2013

Progress Report for:
Measure Q2010 and Measure R2010
Bond Implementation and Reconciliation Program

By: TELACU Construction Management 604 N. Eckhoff St.

Orange, CA 92868

tel: 714.541.2390 fax: 714.541.9411 tcm.TELACU.com









SANTA BARBARA UNIFIED SCHOOL DISTRICT MEASURE Q AND MEASURE R BOND IMPLEMENTATION AND RECONCILIATION PROGRAM PROGRESS REPORT 2/6/13

TABLE OF CONTENTS

EXECUTIVE SUMMARY

SECTION 1 EXPENDITURE RECONCILIATION

Measure Q 2010

Bond Program Summary

Attachment "Q-1" Expenses through 1/31/2012

Attachment "Q-2" & "Q-3" Pending and Future Cost Projection

Measure R 2010

Bond Program Summary

Attachment "R-1" Expenses through 1/31/2012

Attachment "R-2" & "R-3" Pending and Future Cost Projection

SECTION 2 PROJECT PRIORITY MATRIXES

SECTION 3 SITE PROJECT ASSESMENT REPORTS WITH BUDGETARY ESTIMATES Secondary School Reports:

Goleta Valley Junior High School La Colina Junior High School La Cumbre Junior High School Dos Pueblos High School San Marcos High School

Santa Barbara Junior High School Santa Barbara High School

Elementary School Reports:

Adams Elementary School Adelante Charter School Cleveland Elementary School Franklin Elementary School

Harding University Partnership School

McKinley Elementary School
Monroe Elementary School
Peabody Charter School
Roosevelt Elementary School
Santa Barbara Charter School
Santa Barbara Community Academy
Washington Elementary School

TELACU Construction Management 604 N. Eckhoff Street, Orange, CA 92868 T 714.541.2390 F 714.541.9411 www.TELACU.com





SECTION 4 SYSTEM ASSESMENT REPORTS

4.1 Roofs

4.2 Asphalt / Playgrounds / Parking Lots

4.3 Mechanical Systems





SANTA BARBARA USD MEASURE Q AND MEASURE R BOND IMPLEMENTATION AND RECONCILIATION PROGRAM PROGRESS REPORT 2/6/13

EXECUTIVE SUMMARY

This Progress Report includes reporting and activity completed by TELACU Construction Management, for Task 1 Activity completed through 2/6/2013:

Review and reconciliation of bond program expenditures through 12/31/2012 and Projected Cost to complete bond projects

REPORT SECTION 1

Bond Program Summaries of Revenue and Expenses for both Measure Q and Measure R are provided in Section 1.

Summaries include tabulation of expenses and projected costs to complete projects. Source document for revenue and expenses through 12/31/13 was provided to TELACU from SBUSD Fiscal services.

Review includes:

Specific Site Project costs and Undesignated Expenses are summarized in Attachment "Q-1" "Q-2", for Measure Q, and in Attachment "R-1" for Measure R.

Project costs to complete are a compilation of figures provided in reports from SBUSD Fiscal Services, and Budgetary Estimates provided by TELACU.

Budgetary Estimates are summarized in Attachments "Q-2" and Attachment "R-2".

Revised & Updated Project Priority Matrixes

REPORT SECTION 2

A Priority Matrix identifying each Site Project was provided to TELACU by SBUSD Facilities. We understand these lists were developed by Facilities and provided to the Board in 2012.

Priority Matrixes have been updated to reflect status of certain projects already completed, those submitted to DSA for review and permit issuance, and those which have been released for design.

Budgetary Estimates for Measure Q and Measure R projects

REPORT SECTION 3

Each Site Project has been evaluated and assigned a Budgetary Estimate for completion.

The process to arrive at the Budgetary Estimates is:

- 1. TELACU has inspected each site and met with Principal or other staff on site to obtain their perspective and input on projects and to evaluate facility conditions.
- 2. Consultation with architects and engineers involved with the projects and regularly contracting with SBUSD, including their Estimates for specific projects.
- 3. Consultation with SBSD staff from Planning, and from Maintenance and Operations.
- 4. Consultation and estimates from specialty vendors with history of providing services to SBSD.
- 5. Review and evaluation of costs data through 12/31/12 per reports provided by SBSD Fiscal Services.
- Budgetary Estimates include factors
 10% Contingency over projected costs
 Cost Escalation through a projected date of completion 30% Soft Costs.

Narrative Reports for each Site Project are included in Section 3.

Reports for Measure Q projects are complete. Reports for Measure R projects are in compilation.





SANTA BARBARA USD MEASURE Q AND MEASURE R BOND IMPLEMENTATION AND RECONCILIATION PROGRAM PROGRESS REPORT 2/6/13

EXECUTIVE SUMMARY

Systems Approach Assessments:

SECTION 4

In addition to the Site Project Reports of Section 3, different systems and categories of District Facilities are evaluated for determining age, general condition and specific conditions requiring attention and near-term outlay of expense, and for developing schedules with costs projections for maintenance and replacement.

TELACU will complete the Systems Assessments and provide Budgetary Estimates for consideration by the Board.

The following is completed in conjunction with the Site Project assessments of Section 2: Roofs:

All school site roofs are inspected.

Inspection Report with recommendations is completed. Much of this reporting has been transferred to Site Project reports when a specific need was identified in the Project Priority Matrixes.

Paving and Site:

All school site asphalt-paved and other site surfaces are inspected.

Inspection Report is in process of completion. As with the roof inspection data, much has been transferred to Site Project reports when a specific need was identified in the Project Priority Matrixes.

Exterior Building Envelope:

This category includes the thermal and moisture closure of the buildings, protective and aesthetic exterior finishes, such as painting and waterproofing.

Initial Inspection all sites completed.

Inspection Report is in process of completion.

Historical sites Santa Barbara High School, Santa Barbara Junior High School, La Cumbre High School and Mc Kinley Elementary all had exterior painting and window replacement. Peabody Elementary had an exterior painting project. Much of the data gathered for these sites is in the Reports in section 3. Non-historical site Dos Pueblos likewise had an exterior painting project, with Report in Section 3.

Mechanical and Plumbing Systems:

Initial Inspection all sites completed.

Detailed inspection and reports for sites with specific MQ projects completed: Santa Barbara High School, Santa Barbara Junior High School San Marcos High School, La Cumbre Junior High School (Kitchen Exhaust project), and Peabody Elementary.

Inspection Report for remainder of site HVAC system is in process of completion.

TELACU intends to continue developing categories in addition to those listed above for assessment and reporting





SANTA BARBARA USD MEASURE Q AND MEASURE R BOND IMPLEMENTATION AND RECONCILIATION PROGRAM PROGRESS REPORT 2/6/13

EXECUTIVE SUMMARY

Task 1 Assignment remaining to complete:

Continuing Progress: Completion of Assessment

- 1. Site and Project Reports for Measure R
- 2. Systems reviews and assessment

Remaining to Complete:

- 1. Implementation Plan
- 2. Master program schedule
- 3. Cash flow forecast
- 4. Project completion schedule.

TASK 1 ASSIGNMENT

- 1. Reconcile all costs to date for Measure Q and Measure R
 - A. For completed projects, determine total final costs
 - B. For projects in progress
 - i. Develop or Review Project Budget
 - ii. Determine Cost to complete
 - iii. Create completion schedule
- 2. Development of Implementation Plan for all Future Projects under Measure Q and Measure R
 - A. Develop or Review project budgets
 - B. Develop Master Program Schedule including Cash Flow, Expenditure Forecast and other financial tools
 - C. Support District in Prioritization of Projects





MEASURE Q PROJECTS PRIORITY MATRIX 1/23/2013

		Code	Past			Alleviate					
		Safety	Bond	Shovel	Program	General		ADA or	Matching		Protect
Goleta Valley JHS	SCORE	DSA	Priority	Ready	Parity	Fund	Green	Settlement	Funds	CTE	Asset
Exterior Waterproofing	2		Х								Х
ICM Upgrade	on hold	Х	Х								
Site Drainage	2		Х								Х
Upgrade Locks/Keys	90%	Х									Х
VOIP Phone System	2				Х	Х					
A/C for Servers	2				х						Х
Photovoltaics/Solar	2					х	Х				
Playground Asphalt	1				Х						Х
Roof Replacement	1										Х
Sewer Replacement	1			•							Х
Wireless Internet	Complete				Х						

		Code Safety	Past Bond	Shovel	Program	Alleviate General		ADA or	Matching		Protect
La Colina JHS	SCORE	DSA	Priority	Ready	Parity	Fund	Green	Settlement	Funds	CTE	Asset
ICM System Replacement	on hold	Х	Х		Х						
Hillside Stabilization	Complete										
Photovoltaics/Solar	2					х	Х				
Portable Replacement (Quad)	2	Х			х						
Upgrade Locks/Keys	2	Х									х
VOIP Phone System	2				х	х					
Kitchen Walk-in Cooler Replacement	1	Х									
Parking Lot Asphalt	Complete										х
Roof Replacement	1										х
Site Drainage	Complete										Х
Wireless Internet	Complete				Х						

		Code Safety	Past Bond	Shovel	Program	Alleviate General		ADA or	Matching		Protect
La Cumbre JHS	SCORE	DSA	Priority	Ready	Parity	Fund	Green	Settlement	Funds	CTE	Asset
Playground Asphalt	3	Х			х						Х
Remaining Lawsuit ADA	Complete										
Windows Replacement	3	Х	Х								Х
Exterior Painting / Gutters	2		Х								Х
ICM Replacement	on hold	Х	Х								
Photovoltaics/Solar	2					Х	х				
Upgrade Locks/Keys	90%	Х									х
VOIP Phone System	2				х	Х					
Ceiling Replacement (hall/café)	1	Х									
Classroom Modernization	1				х						
Kitchen Exhaust	1	Х									
Parking Lot Asphalt	1										х
Roof Replacement	1										Х
Site Drainage	Complete										х
Theater Modernization	in design				Х						
MP Room Modernization	1				Х						
Wireless Internet	Complete				Х						





MEASURE Q PROJECTS PRIORITY MATRIX 1/23/2013

		Code Safety	Past Bond	Shovel	Program	Alleviate General		ADA or	Matching		Protect
Santa Barbara JHS	SCORE	DSA	Priority	Ready	Parity	Fund	Green	Settlement	Funds	CTE	Asset
ADA & RR Upgrades	3	Х			Х			х			
Computer Lab HVAC	2	Х			х						
Heating/Ventilation Replacement	2	Х			Х						
Kitchen Modernization	2	Х			х						
Photovoltaics/Solar	2					х	Х				
Classroom Mod Science/PE	in design				Х						
Classroom Modernization	1				х						
Exterior Paint	1										Х
Locker Room Renovation	1				х						
MP Room Modernization	1				х						
Playground Asphalt	in design										х
Roof Replacement	1										Х
Site Drainage	1										Х
Upgrade Locks/Keys	2	Х									Х
VOIP Phone System	2				Х	Х					
Window/Skylight Replacement	1										х
Wireless Internet	Complete				Х						

		Code	Past	Ch I	D	Alleviate		404	N d = 1 = le le = =		D
		Safety	Bond	Shovel	Program	General		ADA or	Matching		Protect
Dos Pueblos HS	SCORE	DSA	Priority	Ready	Parity	Fund	Green	Settlement	Funds	CTE	Asset
Asphalt Replacement	Complete	х			х						Х
HVAC Replacement (A/C comp)	Complete	Х	Х		х						
Fire Alarm Upgrade	2	х									Х
Photovoltaics/Solar	2					х	Х				
Replace Tennis Courts	2			Х	х						
Security Cameras	2	Х									Х
Shower/Locker/RR Rehab	2	Х			Х						
Stadium RR Addition	2	Х			х						
Upgrade Locks/Keys	2	Х									Х
VOIP Phone System	in progress				х	х					
Classroom Mod Ph II	1				х						
Exterior Paint	1										Х
ICM System Replacement	on hold	Х									
Kitchen Modernization	1	Х									
Roof Replacement	1										Х
Wireless Internet	Complete				Х						

		Code Safety	Past Bond	Shovel	Program	Alleviate General		ADA or	Matching		Protect
San Marcos HS	SCORE	DSA	Priority	Ready	Parity	Fund	Green	Settlement	Funds	CTE	Asset
New Wing to Replace Portables	Complete	Х		Х	Х					х	
ADA & RR Upgrades	Complete	Х		Х	Х			х			
Asphalt Replacement	3	Х			х						х
VOIP Phone System	2				Х	Х					
Upgrade Locks/Keys	65%	Х									Х
Security Cameras	2	Х									Х
Roof Repair	2	Х									Х
Photovoltaics/Solar	2					х	Х				
Library Modernization	2				х						Х
HVAC Upgrade	2	Х			х						
Gym Roof Replacement	in progress	Х									Х
Electrical System Upgrade Phase I	Complete	Х			х						
Electrical System Upgrade Phase II	In design	Х			х						
Wireless Internet	Complete				X						
Water Line Replacement	Complete	Х									
Sewer line Replacement	1	Х									
Site Drainage Phase I	Complete										Х
Site Drainage Phase II & ADA pathway	in design										Х
Classroom Modernization	1				Х						





MEASURE Q PROJECTS PRIORITY MATRIX 1/23/2013

		Code Safety	Past Bond	Shovel	Program	Alleviate General		ADA or	Matching		Protect
Santa Barbara HS	SCORE	DSA	Priority	Ready	Parity	Fund	Green	Settlement	Funds	CTE	Asset
Health Office RR Upgrade	4	Х		Х	Х			Х			
Kitchen Upgrade	Complete	Х	Х	Х	Х						
Remaining Lawsuit ADA	Complete	Х			Х			Х			
Green Academy Renovation	3				х			Х		Х	
Asphalt Replacement	2	х									х
Boiler Upgrades/relocation	2	Х			х						
Classroom Modernization Phase II	2			Х	Х						
Exterior Fencing	2	Х									Х
Field House Modernization	2	Х			Х						
HVAC Upgrades	2	Х			х						
Photovoltaics/Solar	2					х	Х				
Security Cameras	2	Х									Х
Stadium Upgrade	2	Х			х						
Upgrade Locks/Keys	2	Х									Х
VOIP Phone System	2				Х	Х					
Exterior Paint (main)	1										Х
Gym Renovation (inc. floor)	in design				х						
Roof Replacement	1										Х
Theater Modernization	1				Х						
Window Replacement (main, 20, 30)	1										Х
Wireless Internet	Complete				Х						



BOND PROGRAM SUMMARY

Measure Q2010

r-Approved	l Bond Total				\$	75,000,000
	MQ 2010 REVENUE TO DATE	through 12/31/2012			\$	42,199,181
	EXPENSES THROUGH 12/31/201	2 (ATTACHMENT "Q-1")			\$	27,704,109
		COMPLETED PROJECTS UNDESIGNATED EXPENSES	\$ \$	26,546,146 1,157,963		
	REMAINING REVENUE: REVENUE	E LESS EXPENSES TO DATE			\$	42,199,181
Add:	FUTURE BOND SALES REVENUES				\$	35,001,658
=	* AVAILABLE FOR PLANNED PRO	DIECTS UPON FULL BOND SALES			\$	77,200,839
Less:	MQ Pending & Future Projects	(ATTACHMENT "Q-2")			\$	224,607,110
Less:	** MQ PROJECTED EXPENSES NO (ATTACHMENT "Q-3")	OT INCLUDED IN MEASURE Q PROJEC	CTS LIST		\$	44,349,066
		UNDESIGNATED EXPENSES	\$	1,510,574		
		ADDITIONAL SITE PROJECTS	\$	1,821,730	-	
		PORTABLE REPLACEMENTS	\$	38,593,412	-	
		ASPHALT PAVING	\$	639,750		
		ROOFING PROJECTS	\$	1,783,600	•	
=	MQ FUNDING SHORTFALL FO	OR PLANNED PROJECTS			\$	301,807,949

FOOTNOTES:

All Revenue and Expense figures are per SBSD Fiscal Services Reports 12/31/2012

- * 1. Amount for Future Bond Sales equals Voter-Approved total less sales to date
 - Future Bond Sale Revenues shown <u>does not</u> include any sources other than bond sales Revenues (such as State 2. Matching Funds, grants, or other fundraising)

Refer to Attachment "Q-3" for Budgetary Estimates for the following NOT SPECIFICALLY INCLUDED ON Measure Q

* Project List

- 1. Projected Undesignated Expenses are calculated using the ratio of Undesignated Expenses to date to Total Expenses to date, as applied to totals for Pending and Future Projects
- 2. Site Projects not on the Priority Project Matrix
- 3. Replacement of Portable Classroom buildings with permanent Buildings
- 4. Asphalt surface paving projects
- 5. Roof Replacement projects





ATTACHMENT Q-1

MEASURE Q SECONDARY SCHOOLS EXPENSES THROUGH 12/3/2013

COMPLETED PROJECTS AND UNDESIGNATED EXPENSES

1. SITE PROJECTS COMPLETED

MG			SITE	SITE
CODE	SITE	PROJECT	PROJECTS	TOTAL
01-0000	La Colina JHS	Undesignated Expenses	\$ 236.65	
5705	La Colina JHS	Hillside stabiliz.& Site Drainage(south)	\$ 38,791.25	
5707	La Colina JHS	Site drainage (west)	\$ 117,426.75	
5708	La Colina JHS	Wireless Access	\$ 220,509.46	
5720	La Colina JHS	Parking Lot Asphalt	\$ 1,083,766.42	\$ 1,460,730.53
02-0000	La Cumbre JHS	Undesignated Expenses	\$ 1,485.80	
5709	La Cumbre JHS	Wireless Access	\$ 210,286.19	
5723	La Cumbre JHS	ADA upgrades / Remaining Lawsuit	\$ 2,603.33	\$ 214,375.32
03-0000	San Marcos HS	Undesignated Expenses	\$ 7,697.80	
5702	San Marcos HS	New Classroom Addition (B Wing)	\$ 9,906,736.15	
5702	San Marcos HS	Electrical Infrastructure Phase 1	\$ 155,481.64	
5702	San Marcos HS	Water Line Replacement	Inc. w/ 5702	
5710	San Marcos HS	Wireless Access	\$ 388,807.16	
5718	San Marcos HS	Site Drainage Phase 1	\$ 82,487.38	\$ 10,541,210.13
04-0000	Santa Barbara HS	Undesignated Expenses	\$ 332,982.80	
5704	Santa Barbara HS	Kitchen Renovation	\$ 5,053,666.67	
5711	Santa Barbara HS	Wireless Access	\$ 328,614.85	
5725	Santa Barbara HS	Remaining ADA Lawsuit	\$ 55,718.40	
5737	Santa Barbara HS	New Roofing Phase 1: Nopal Building	\$ 223,102.25	\$ 5,994,084.97
05-0000	Santa Barbara JHS	Undesignated Expenses	\$ 7,875.48	
5708	Santa Barbara JHS	Wireless Access	\$ 237,457.69	\$ 245,333.17
06-0000	Goleta Valley JHS	Undesignated Expenses	\$ 943.90	
5713	Goleta Valley JHS	Wireless internet	\$ 226,414.59	\$ 227,358.49
07-0000	Dos Pueblos HS	Undesignated Expenses	\$ 41,103.70	
5701	Dos Pueblos HS	HVAC Replacement	\$ 6,287,541.35	
5703	Dos Pueblos HS	Faculty Lot Asphalt	\$ 660,666.17	
5706	Dos Pueblos HS	Cafeteria Road Construction	\$ 481,357.27	
5714	Dos Pueblos HS	Wireless Access	\$ 338,474.05	\$ 7,809,142.54
08-0000	La Cuesta HS	Undesignated Expenses	\$ 4,203.00	
5714	La Cuesta HS	Wireless Access	\$ 49,707.36	\$ 53,910.36
	TOTAL Completed Projects			\$26,546,145.51

Source: Fund 27 Project Costs Summary 12/31/12 SBSD Fiscal Services





ATTACHMENT Q-1

MEASURE Q SECONDARY SCHOOLS EXPENSES THROUGH 12/3/2013

COMPLETED PROJECTS AND UNDESIGNATED EXPENSES

2. UNDESIGNATED EXPENSES

MG	District Undesignated MQ		Encumbered 2012-	=
CODE	Expenses:	Life-To-Date	2013	
2210/2310	Classified Salaries	\$235,995.41	\$ 99,280.20	
2910	Other Classified Salaries	\$92,719.68	\$ 36,803.28	
3000-3999	Benefits	\$112,026.19	\$ 44,871.04	
4400/4450	Equipment & Computers	\$2,577.29	\$ 493.31	
5810	Contracted Services	\$374,373.98	\$ 14,000.00	
5825	Audit Fee	\$7,722.72	\$ 4,000.00	
5910	Postage	\$45.81	\$ -	
6209	Engineering	\$191.25	\$ 2,308.75	
6214	Others	\$13,582.42	\$ 158.72	
6215	Main Construction	\$0.00	\$ 21,486.45	
6216	Management	\$48,203.60	\$ 10,860.00	
6218	Other Construction	\$11,844.00	\$ 23,913.54	
6400	Equipment	\$505.68	\$ -	
	Totals	\$899,788.03	\$ 258,175.29	
	TOTAL Undesignated, Life-to-I	Date + Encumbered		\$1,157,963.32

Source: Fund 27 Project Costs Summary 12/31/12 SBSD Fiscal Services





ATTACHMENT Q-2

MEASURE Q SECONDARY SCHOOLS MEASURE Q SECONDARY SCHOOLS PENDING AND FUTURE PROJECTS

Sources: Measure Q Projects Priority Matrix 1/23/13 Site Project Reports - Budgetary Estimates

TOTAL BUDGETARY ESTIMATE, MEASURE Q PENDING AND FUTURE

PROJECTS		\$ 224,607,110
TOTALS BY SITE		
La Colina Junior High School	\$ 8,398,787	
La Cumbre Junior High School	\$ 29,951,759	
San Marcos High School	\$ 33,311,931	
Santa Barbara High School	\$ 64,765,931	
Santa Barbara Junior High School	\$ 38,266,963	
Goleta Valley Junior High School	\$ 6,851,828	
Dos Pueblos High School	\$ 43,054,912	
La Cuesta Continuation HS	\$ 5,000	

Refer to SUMMARY and ATTACHMENT Q-3 for:

La Colina Junior High Total

ADDITIONAL RECOMMENDED PROJECTS NOT ON MASURE Q PROJECTS LIST PORTABLE CLASSROOM REPLACEMENTS NOT ON MEASURE Q PROJECTS LIST ROOF REPLACEMENT AND MAINTENANCE NEEDS NOT ON MEASURE Q PROJECTS LIST ASPHALT PAVING NEEDS NOT ON MEASURE Q PROJECTS LIST

PROJECTS, BY SITE - PENDING AND FUTURE PROJECTS FROM MEASURE Q PROJECTS LIST

BUDGETARY MG SITE & PROJECT **ESTIMATE STATUS COMMENTS** CODE 001 La Colina Junior High On hold pending resolve of Beta Test using JIVE system VOIP on Dos 5730 Intercom Replacement \$ 393,250 Design on hold Pueblos to accommodate Intercom Material Purchase Estimate from District F&O Lock and Key Upgrade \$ 17.000 Assessment Photovoltaics / Solar \$ 2,000,000 Assessment Demolition of old bldgs. Is completed 5729 Replace Quad Portables \$ 1,870,979 Assessment VOIP phone system \$ 10,000 Assessment E-Rate Project; infrastructure allowance \$ 270,257 Assessment Kitchen / Walk - in coolers replacement \$ 3,837,300 Assessment ----Roof Replacement

8,398,787

\$

CODE	002 La Cumbre JHS			
5726	Theater Modernization	\$ 2,964,924	Permit pending	IN DSA
5731	Intercom Replacement	\$ 350,350	Design on hold	On hold pending resolve of Beta Test using JIVE system VOIP on Dos Pueblos to accommodate Intercom
5717	Parking Lot Asphalt	\$ 528,710	Assessment	
	Play Ground Asphalt	\$ 261,486	Assessment	
	Exterior - Painting / Gutters	\$ 904,826	Assessment	
	Window Replacement	\$ 6,189,182	Assessment	
	Photovoltaics / Solar	\$ 2,000,000	Assessment	
	Lock and Key Upgrade	\$ 24,000	Assessment	Material Purchase Estimate from District F&O
	VOIP phone system	\$ 10,000	Assessment	E-Rate Project; infrastructure allowance
	Ceiling Replacement	\$ 83,618	Assessment	
	Classroom Modernizations	\$ 13,703,433	Assessment	
	Kitchen Exhaust	\$ 485,098	Assessment	
	Multi-Purpose Room Modernization	\$ 984,256	Assessment	
	Roof Replacement	\$ 1,461,876	Assessment	
	La Cumbre Junior High Total	\$ 29,951,759		





ATTACHMENT Q-2 MEASURE Q SECONDARY SCHOOLS

CODE	003 San Marcos HS			
5702	Classroom Addition Phase III	\$ 350,000	DSA Approved	Final Phase, portable bldgs. move on site & off site to Adams ES
5375	Gymnasium Roof Replacement	\$ 533,984	In Construction	
5724	Electrical Infrastructure Phase 2	\$ 1,732,800	DSA Approved	
5721	ADA Ramps & Site drainage (Phase II)	\$ 350,575	DSA Approved	
	Lock and Key Upgrade	\$ 170,000	Assessment	Material Purchase Estimate from District F&O
	Photovoltaics / Solar + Metal Roofs	\$ 6,365,916	Assessment	A, B,C,D,E,F,I bldgs.; 02/12, PMSM study
	VOIP phone system	\$ 40,000	Assessment	E-Rate Project; infrastructure allowance
	Sewer Line Replacement	\$ 50,000	Assessment	
	Senior lot asphalt replacement	\$ 604,517	Assessment	
	Roof Structure Repairs	\$ 471,290	Assessment	
	HVAC Replacement	\$ 3,390,437	Assessment	
	ADA Ramp & Restroom Upgrades	\$ 1,099,308	Assessment	
	Asphalt Replacement / Restoration	\$ 2,098,082	Assessment	
	Library Modernization	\$ 3,128,496	Assessment	
	Classroom Modernization	\$ 12,767,400	Assessment	
	Security Cameras	\$ 159,125	Assessment	
· <u> </u>	San Marcos High School Total	\$ 33,311,931	·	

MG

IVIG				
CODE	004 Santa Barbara HS			
5725	Gym renovation	\$ 1,209,452	Permit pending	IN DSA
	Gym Renovation, Recommended concurrent projects	\$ 642,356	Assessment	
5719	Field House Modernization	\$ 4,863,144	Assessment	
	Lock and Key Upgrade	\$ 205,000	Assessment	Material Purchase Estimate from District F&O
	VOIP phone system	\$ 40,000	Assessment	E-Rate Project; infrastructure allowance
	Photovoltaics / Solar	\$ 5,000,000	Assessment	
	60's wing structural and roof repair	\$ 903,956	Assessment	
	Roofing Replacement	\$ 1,892,259	Assessment	
	Window Replacement	\$ 7,739,274	Assessment	Main Building +20's & 30's Wings
	Green Academy renovation	\$ 981,552	Assessment	
	Boiler Replacement	\$ 4,212,600	Assessment	
	HVAC Upgrades	\$ 830,232	Assessment	
	Theater Modernization	\$ 5,153,769	Assessment	
	Exterior Painting	\$ 1,044,758	Assessment	
	Health Office	\$ 267,696	Assessment	
5724	Peabody Stadium Modernization	\$ 11,191,448	Assessment	
	Asphalt Replacement / Restoration	\$ 1,976,117	Assessment	
	Classroom Modernizations II	\$ 16,080,279	Assessment	
	Security Cameras	\$ 182,039	Assessment	
	Exterior Fencing	\$ 350,000	Assessment	
	Santa Barbara High School Total	\$ 64,765,931		





ATTACHMENT O-2

			ATT	ACHMENT Q-2	
			MEASURE Q	SECONDARY SCHO	OLS
MG					
CODE	005 Santa Barbara JHS				
5727	Science Classroom Modernizations.	\$	910,126	Permit pending	IN DSA
	ADA & Rest room upgrades	\$	350,000	Assessment	
	Computer Lab HVAC	\$	230,412	Assessment	
	HVAC Replacement	\$	3,317,646	Assessment	
	Kitchen Modernizations	\$	4,932,865	Assessment	
	Photovoltaics / Solar	\$	2,000,000	Assessment	
	Lock and Key Upgrade	\$	105,000	Assessment	Material Purchase Estimate from District F&O
	VOIP phone system	\$	10,000	Assessment	E-Rate Project; infrastructure allowance
	Classroom Modernizations	\$	9,000,237	Assessment	
	Exterior Paint	\$	943,480	Assessment	
	Locker Room renovation	\$	3,251,644	Assessment	
	MPR modernizations	\$	2,430,019	Assessment	
	Roof Replacement	\$	1,083,575	Assessment	
5716	Playground Asphalt / Site Drainage	\$	2,095,445	Assessment	
	Window Replacement	\$	7,606,514	Assessment	
	Santa Barbara J H S Total	\$	38,266,963		
5732	Intercom Replacement	\$	357,500	Design on hold	On hold pending resolve of Beta Test using JIVE system VOIP on D Pueblos to accommodate Intercom
					. debies to descrimentate intersection
	Waterproofing	\$	65,000	Assessment	
	Site Drainage	\$	1,136,850	Assessment	
	Lock and Key Upgrade	\$	47,000	Assessment	Material Purchase Estimate from District F&O
5740	VOIP phone system	\$	25,000	Assessment	E-Rate Project; infrastructure allowance
	A/C for Servers	\$	223,464	Assessment	
	Photovoltaics / Solar	\$	2,000,000	Assessment	
	Playground asphalt	\$	186,160	Assessment	
	Roof Replacement	\$	2,386,814	Assessment	
	Sewer Replacement	\$	424,040	Assessment	
	Goleta Valley J H S Total	\$	6,851,828		
MG CODE	007 Dos Pueblos HS				
5734	Gym Roof	\$	645	In Construction	Incidental Expense. Related to HVAC Replacement project
5728	Lock and Key Upgrade	\$	91,000	Assessment	Material Purchase Estimate from District F&O
5739	VOIP phone system	Ś	40,000	Assessment	F-Rate Project: infrastructure allowance: Reta Testing IIVE system

IVIG					
CODE	007 Dos Pueblos HS				
F724	Cum Book	ć	645	In Construction	Incidental Expense. Related to HVAC Replacement project
5734	Gym Roof	\$	043	iii Construction	incluental Expense. Related to HVAC Replacement project
5728	Lock and Key Upgrade	\$	91,000	Assessment	Material Purchase Estimate from District F&O
5739	VOIP phone system	\$	40,000	Assessment	E-Rate Project; infrastructure allowance; Beta Testing JIVE system
	Showers & Locker Rooms	\$	3,765,475	Assessment	
	Intercom Replacement	\$	250,250	Design on hold	On hold pending resolve of Beta Test using JIVE system VOIP on Dos Pueblos to accommodate Intercom
	Photovoltaics / Solar	\$	5,000,000		
	Tennis Courts	\$	773,344	Assessment	
	Kitchen Modernizations	\$	4,670,398	Assessment	
	Classroom Mod II	\$	20,483,247	Assessment	
	Exterior Paint	\$	928,013	Assessment	
	Stadium Restroom	\$	1,415,014	Assessment	
	Security Cameras	\$	182,039	Assessment	
	Asphalt Replacement	\$	1,284,162	Assessment	
	Roof Replacement	\$	4,171,326	Assessment	
· ·	Dan Danklan III-k Cakaal Taral	Ċ	42.054.043		

Dos Pueblos High School	Total	\$ 43,054,912

MG				
CODE	008 La Cuesta Continuation HS			
5741	VOIP phone system	\$ 5,000	Assessment	E-Rate Project; infrastructure allowance
	La Cuesta High School Total	\$ 5,000		





ATTACHMENT Q-3 MEASURE Q SECONDARY SCHOOLS PROJECTED EXPENSES NOT INCLUDED IN MEASURE Q PROJECTS LIST

1. Projected Undesignated Expenses on remaining Mo	easure Q expenditures	\$1,510,574	
2. Projects not included in the Measure Q Project List	t	\$1,821,730	
3. Portable Classroom Replacement with new Perma	anent Buildings	\$38,593,412	
4. Asphalt Surfaces and Paving		\$639,750	
5. Roofing		\$1,783,600	
(Detail Below)	TOTAL	\$44,349,066	

1. Projected Undesignated Expenses on remaining Measure Q expenditures

Undesignated Expenses through 12/31/12	\$	1,302,991
Total MQ Expenses through 12/31/12	\$	34,718,015
Ratio:		3.75%
140) / 1	¢	40,281,985
x MQ Voter-Approved fund remaining	۲	40,201,303
= Estimated future MQ Undesignated Expense	٠,	40,201,303

2. Projects not included in the Measure Q Project List

This section provides Budgetary Estimate for Projects identified subsequent development of the Measure Q Projects List.

001 La Colina Junior High

La Colina Site Stabilization Phase III: \$ 493,350

Phases 1 & 2 are completed. These phases constructed drainage facilities at the west and south east portions of the property. has manifested at the O.A.S. playground area. Geotechnical investigation is underway, engineering design & specifications pending

Sub grade failure

Soils Investigation	\$ 15,000
Site Clearing and materials disposal	\$ 30,000
Soils over excavation, re-compaction & grading	\$ 150,000
Construct drainage facilities, connect to existing site storm drain system.	\$ 30,000
Asphalt paving 16,000 sf x \$ 7.50 / S.F.	\$ 120,000
Contingency, 10%	\$ 34,500
General Conditions, 12%	\$ 45,540
Subtotal	\$ 379,500
Soft Costs, 30%	\$ 113,850
Estimate Total	\$ 493,350

002 La Cumbre JHS

Theater HVAC Equipment Replacement (Frank Schipper Construction Estimate 1/16/2013)	\$ Scope of work on the design drawings now in DSA for approval did not include replacement of the equipment for the Theater.
Contingency (included in Contractor Estimate)	\$ - Included in Contractor Estimate
Soft Costs 30%	\$ 126,600
TOTAL	\$ 548,600





ATTACHMENT Q-3 MEASURE Q SECONDARY SCHOOLS

003 San Marcos HS					
Gymnasium Roof beam structural repairs			\$ 364,780		
Roof beams are deteriorated at connections to the h	oase plates a	at the foundat	ons on v	west side of build	ing. Structural engineer has been engaged for evaluation and to design repairs.
Beam repairs, 10 x \$ 20,000 each	\$	200,000	-		
Shoring and temporary building support	\$	10,000	-		
Repair and replacement of finishes, landscaping	\$	20,000	-		
Contingency, 10%	\$	23,000	-		
General Conditions, 12%	\$	27,600	_		
Subtotal	\$	280,600	-		
Soft Costs, 30%	\$	84,180	-		
Estimate Total	\$	364,780	<u>-</u> -		
007 Dos Pueblos HS					
Covered Walkway Skylight Replacement			\$	415,000	Refer to Project Report . We recommend this be completed concurrent with the re-roofing project

3. Portable Classroom Replacement with new Permanent Buildings

This section provides a Budgetary Estimate for:

- 1) demolition and removal of existing portable classroom buildings
- 2) Replacement of classroom space with new single-story classroom buildings

BUDGETAF	RY ESTIMATE :	\$	38,593,412	_
Total Port	able Units	52		_
Gross Tota	ıl Square Footage	53,360	(58,696)	(Square Footage will be adjusted in computation of replacement buildings space to allow for 10% additional S.F. of support spaces: mechanical & electrical, restrooms, janitorial, storage spaces)
	Abatement	\$ 130,000		Sampling, Lab work& Reports + abatement @ \$2,500 each.
	Demolition and disposal	\$ 780,000		\$15,000 per unit
	Construct New Permanent Buildings	\$ 23,478,400		\$ 400 per sq. ft. + 10% additional square for support spaces: mechanica & electrical, restrooms, janitorial, storage spaces
	Utilities & Site Work	\$ 2,600,000		\$ 50,000 allowance per unit
	Subtotal	\$ 26,988,400		
	Contingency 10%	\$ 2,698,840		
	Soft Costs, 30%	\$ 8,906,172		
	Total	\$ 38,593,412		

SITE	TABLE BUILDING COUNT BY SITE			
001	La Colina Junior High	# UNITS	SF	OAS Units count
	507	1	960	
	508	1	960	
002	La Cumbre JHS	\$ -		SBCA Units coun

OAS Units counted on Elementary Matrix

SBCA Units counted on Measure R Attachment "R-3"





ATTACHMENT Q-3 MEASURE Q SECONDARY SCHOOLS

Portables (continued)

003	San Marcos HS			
	Š1		960	Not counted: to be moved to Adams ES
	S2		960	Not counted: to be moved to Adams ES
	S3		960	Not counted: to be moved to Adams ES
	S4	1	960	
	S5	1	960	
	S6	1	960	
	S7	1	960	
	S village Restroom Building	1	480	
	12	1	960	
	14	1	960	
	16	1	960	
	18	1	960	
	I 10	1	960	
	12 & 14	2	1920	
	l 11	1	960	
	l 13	1	960	
	I Village Restroom	1	480	
004	Santa Barbara HS			
	40A & 40 B - CDC	2	2000	
	41	1	960	
	42	1	960	
	43	1	960	
	53	1	960	
	54	1	960	
005	Santa Barbara JHS			
	CDP	1	1920	
	ITS	1	1920	
006	Goleta Valley JHS			SBCC Units counted on Elementary Matrix
	505 & 506	2	1920	
	507 & 508	2	1920	
	801 & 802	2	1920	
	803 & 804	2	1920	
	805 & 806	2	1920	
	807 & 808	2	1920	
007	Dos Pueblos HS			
	Q quad bldg	4	3840	
	Q3	1	960	
	Q4	1	960	
	Q7	1	960	<u></u>
	Q8	1	960	<u></u>
	Q9	1	960	<u> </u>
	Q10	1	960	<u> </u>
	Q11	1	960	<u> </u>
	Q12	1	960	<u> </u>
	Q13	1	960	<u> </u>
	Q Restroom	1	480	<u> </u>
800	La Cuesta Continuation HS			(None)
	TOTALS	52	53,360	<u> </u>





ATTACHMENT Q-3 MEASURE Q SECONDARY SCHOOLS PROJECTED EXPENSES NOT INCLUDED IN MEASURE Q PROJECTS LIST

4. Asphalt Surfaces and Paving TOTAL: \$ 639,750

This section provides a Budgetary Estimate for asphalt parking lots, playgrounds, and other asphalt surfaces which were not specifically identified on the Measure Q Project Lists.

001 La Colina Junior High (O.A.S Surfaces Co	vered in Measure R Site Repor	rts)	
500 Portables area:	\$	29,575	Weathering, cracking, weeds, uplifting. Recommend Crack seal, patch, slurry summer 2013
Playground	\$	145,200	Surface in good condition; recommend seal and re-striping 2014
006 Goleta Valley JHS			
East Parking Lot	\$	66,000	Slurry coated last few years, but heavy weathering of coated surface; Cracking; weeds; some damages to drain elements and curbs. Recommend repairs, crack seal, Patch. Slurry, re-stripe. 44,000 sq. ft.
Main Parking Lot & west side access inlet to deliveries	\$	340,000	Limited areas of pavement failure, extensive cracking, weeds, weathering. Recommend Replace failed areas, crack seal, patch, slurry, stripe Summer 2013 85,000 sq. ft.
800's portable building area	\$	4,400	Fair condition, some cracking & weeds. Recommend minor repairs and slurry coat Summer 2013 4,400 sq. ft.
500's pad+ outdoor surfaces + SBCS Access road areas	\$	25,000	Short term: pavement rehabilitation. Long term: Coordinate with Site Drainage project, plan for portable building replacement Summer 2013 12,500 sq. ft.
008 La Cuesta Continuation HS			
Parking lot off Garden Street	\$	29,575	Weathering, raveling, moderate cracks $\&$ weeds; recommend crack fill, patching, slurry coating Summer 2013

5. Roofing TOTAL \$ 1,783,600

This section provides a Budgetary Estimates for roofs not specifically identified on the Measure Q Project List and not covered in Attachment "Q-2":

003 San Marcos HS

 $Buildings\ M,\ I\ H,\ Cafeteria,\ Library)\ Health\ Center\ \&\ Maintenance,\ \&\ Covered\ Walkways:$

This group of buildings is NOT planned in with the Photovoltaic / Solar installation project. See statement below regarding Buildings Admin., B, C,D, E, F.

All Buildings listed: Hot BUR, 15+ years old. Ponding n some roofs, wind scar and degradation of asphalt.

Recommendations:

Maintenance Repairs needed in 2013; Test and scan for Restoration, or Replace by 2014

Re-Roofing Estimate:

Retrofitting Cost: 84,500 s.f. x \$ 16.00 / s.f.	\$ 1,352,000
Allowance: sheet metal, drainage	\$ 20,000
Subtotal	\$ 1,372,000
Soft Costs, 30%	\$ 411,600
Total, M, I H, Cafeteria, Library, Health Center & Maintenance, &	
Covered Walkways:	\$ 1,783,600

For Buildings A, B, C, D,E & F on site: Not included in tabulation for roofing replacement here.

Project Report for the Photovoltaic / Solar Project in ATTACHMENT "Q-2" includes the cost of new metal roofing on these buildings, which will match the recently completed B-Wing addition. Exception to buildings planned for the Photovoltaic / Solar Project is Building I is a flat roof, and DOES NOT have the built-in roof slope characteristic to A, B, C, D,E & F. Therefore Building I will require re-roofing in coordination with the Photovoltaic / Solar Project)







SHE	LA COLINA JUNIOR HIGH SCHOOL				DATE	1/31/2013
SITE PERSONNEL CONSUL Mr. David Ortiz, Princi		Ray Ramos	s, Lead Custodian			
Kathleen Mc Neil, Kitc		, , , , , , , , , , , , , , , , , , , ,	.,			
Natineen We Wen, Kite	inen manager					
Date last F.I.T. report:	6/4/2009					
F.I.T. Score	98.57%	Rating:	Exemplary			
Issues Identified Deficient	:: None			<u> </u>		
REPORTS REVIEWED:	_					
Haz Mat Report: Asbe	stos and Lead Based Paint R	Report, Channe	el Islands Corp. 9/	27/12		
MANAGEMENT CODE	PROJI	ECT / AREA		PROJ	ECTED COST	STATUS
5707	Site Drainage, West **			\$	117,427	COMPLETED
5705	Site Drainage, South **			\$	35,617	COMPLETED
5720	Parking Lot Asphalt **			\$	1,083,766	COMPLETED
5708	Wireless Access **			\$	220,509	COMPLETED
0000	Undesignated Expense ***			\$	237	COMPLETED
5730	Intercom Replacement			\$	393,250	DESIGN ON HOLD ****
	Lock and Key Upgrade *			\$	17,000	ASSESMENT
	Photovoltaics / Solar, Syst	em allowance	only	\$	2,000,000	ASSESMENT
5729	Replace Quad Portables			\$	1,870,979	ASSESMENT
	VOIP Phone System, Infra	structure allov	vance	\$	10,000	ASSESMENT
	Kitchen Walk-In Replacem	nent		\$	270,257	ASSESMENT
	Roof Replacement			\$	3,837,300	ASSESMENT
	COMPLETED	PROJECTS		\$	1,457,557	
	PROJECTS IN			ς .	393 250	

ASSESSMENT PROJECTS

SITE TOTAL

9,856,344

^{*} Lock and Key Estimates provided by District Facilities and Operations

^{**} Completed project Expenses posted as of 12/31/12

^{***} Undesignated Expenses include costs posted to date. Projected undesignated Expense is tabulated in Attachment "O-3"

^{****} Intercom Replacement design on hold pending Beta test of system using VOIP telephone equipment at Dos Pueblos High School





SITE LA COLIN	A JHS		DATE 1		1/31/2013	
AREA REPLACE	QUAD POR	TABLES	BUDGETARY ESTIMATE:	\$:	1,870,979	
			BY:	TCM	,	
DISTRICT OR CONSULTANT DATA AV	AILABLE:					
Carl Mayrose, Panning Dept. Project	Manager					
INTRODUCTORY COMMENTS:						
Quad grouping of portables was	removed fr	om site. Building pa	ad remains south of Girls Locker room.			
Accessible path of travel is in place	ce at West	and East sides of sid	de of the building pad area.			
RECCOMENDATION:						
Replace with permanent building	;.					
BUDGETARY ESTIMATE:						
ITEM		Est. Cost	Source / Comme	ents		
Demolition and removal costs posted to	date \$	46,055	Costs posted through 12/31/12 for dem	olition of existing	buildings	
New Construction, Permanent building	\$	1,152,000	4340 sq. ft. x \$ 400	/ SF		
Building pad construction	\$	10,000				
Site work, Utilities	\$	50,000				
Contingency, 10%	\$	125,806				
Escalation	\$	55,354	12 months @ 4%	/ yr.		

1,439,215

431,764

1,870,979

FOOTNOTES

\$

\$

\$

SUBTOTAL

Soft Costs 30%

TOTAL ESTIMATED

Estimate is for the quad only: (4) X 24' X 40' = 3,840 SQ. FT. Plus another 500 sq. ft. for ancillary spaces: Mechanical & Electrical Room, janitorial, etc. = 4,340 sq ft total replacement building





SITE	LA COLINA JHS			DATE	1/31/	′2013
AREA / PROJECT	INTERCOM SYSTEM REPLACE	MENT		BUDGETARY ESTIMATE:	\$	393,250
				BY:	TC	CM
DISTRICT OR CONSULTAN	T DATA AVAILABLE:					
Bob Nettles, Santa Barba	ra Electrical Design					
INTRODUCTORY COMME						
•	ercom System was contracted	to Santa Barba	ra Electrical	Design. Completion of d	lesign and su	ibmittal to
DSA for review and ap	oproval is pending.					
5		VOID L. I.				
Design is on hold pen	ding Beta test of system using	VOIP telephone	e equipmen	it at Dos Pueblos High Sci	nool	
Budgetary Estimate a	ssumes proceeding with design	n and installation	on of standa	ard new intercom system		
RECOMMENDATION:						
Complete Beta testi	ng at Dos Pueblos High School	l .				
BUDGETARY ESTIMATE:						
ITEM		E	st. Cost			
Engineer's Estimate		\$	225,000	August 2011		
Conduit & hardware - Allo	owance	\$	50,000			
Contingency 10%		\$	27,500			
SUBTOTAL		\$	302,500			
Soft Costs, 30% of constru	uction cost	\$	90,750			
TOTAL		\$	393,250			



TOTAL ESTIMATED

270,257



SITE ASSESSMENT REPORT MEASURE Q / MEASURE R CAPITAL PROJECTS

SITE	LA COLINA JHS			DATE	1/31/2013
AREA	KITCHEN WAI K-	IN REFRIGERATOR AND FREEZER	REPLACEMENT		
7111271	KITCHEN WALK	THE RECEIVED THE EZEN	ESTIMATE:	\$	270,257
			BY:	K	amran, Inc. / TCM
DISTRICT OR CONSULTANT	DATA AVAILABL	E:			
Inspection of equipment	and price quote	from Kamran, Inc. See below			
Kathleen Mc Neil, Kitche	n Manager				
Steve Vizzolini, SBSD Ele	ctro-Mechanical I	Foreman			
INTRODUCTORY COMMEN					
=	=	nd freezer in one space. Refriger	ator was retrofit	ted and exp	oanded. Freezer was added
in the original serving					
Both are leaking, insula	ation saturated.				
RECCOMENDATION:					
Replace both Walk-in I	Refrigerator and I	Freezer Units			
Contract Architect to	complete schema	tic design and provide schemation	estimate.		
BUDGETARY ESTIMATE:					
ITEM	Est. Cost		Source		Comments
Demolition and	\$ 125,000			Project m	ay include structural work
construction	ÿ 123,000		TCM	and otl	ner changes to building.
New Walk In Equipment	\$ 49,733	Kai	mran, Inc.		
Contingency, 10%	\$ 17,473				
Escalation	\$ 15,684			24 months	@ 4% / yr.
SUBTOTAL	\$ 207,890		-	_	_
Soft Costs, 30%	\$ 62,367				
	1				







KAMRAN AND COMPANY, INC.

FOOD SERVICE AND LAUNDRY EQUIPMENT CONSULTANT AND CONTRACTOR

CA: 687988 B D34 CA: 680904 C38 AZ: ROC112017 BE NV: 52465 C21A NV: 42022 C26A

Kamran Amiri 411 East Montecito Street Santa Barbara, CA 93101

September 12, 2012

Re: La Colina Junior High School Walk In

We are pleased to provide you with the following quote:

Furnish of new walk in cooler and freezer with remote refrigeration: \$30,490.00

Sales Tax: \$2,362.98

Freight: \$1,300.00

\$2,600.00 Removal of old boxes and refrigeration system and haul away:

Installation of new walk in cold boxes and refrigeration including 1 year parts

and labor warranty: \$12,980.00

Exclusions: Electrical, plumbing, roofing, permits and any masonry/building work

Phone: (805) 963-3016 or (800) 480-9418 Fax: (805) 962-5915 Email: info@kamranco.com

411 East Montecito Street Santa Barbara, CA 93101 www.kamranco.com





SITE	LA COLINA JUNIOR HIGH SCHOOL	DATE	1/31/2013
	_		
AREA	ROOFING	BUDGETARY ESTIMATE	\$3,837,300
		RV·	TCM/TREMCO

DISTRICT OR CONSULTANT DATA AVAILABLE:

Inspection of all roof surfaces with Jim Gilday and Joe Razo, Tremco Roofing Products.

Bob Nettles, Santa Barbara Electrical Design

INTRODUCTORY COMMENTS:

This site is nearly identical in construction to Goleta Valley JHS in configuration.

Projects list included only the 500 building. Upon inspection the majority of roofs on site were identified to be in poor to failing condition, with many deficiencies. Roof repairs and replacements are required.

The Budgetary Estimate for the 500 building is totaled separately from the remainder of the campus.

All roofs on site were inspected with Jim Gilday, Technical Services Representative, Tremco Roofing. Mr. Gilday has direct knowledge of roofing projects at the site over the years.

Refer to Roof Report and Roof Diagram for specific conditions and areas.

This Report includes Open Alternative School which utilizes the 400 building.

Deficient conditions requiring repair were discovered on electrical and low voltage system conduits, mechanical piping and system components, improper roof penetrations, and supports or securement of these items. Roof drainage in general is via edge scuppers set at intervals around the perimeter of the roofs. Prevailing condition water discharges from these edge scuppers, falling to grade to be collected by drain inlets. Presence of tree debris material was less than at Goleta Valley JHS. However, significant amounts were discovered in some areas.

RECCOMENDATION:

- 1) Engage Architect or roofing consultant to develop specifications for site, complete bidding and complete roofing projects.
- 2) We recommend roofing project should include roofing for all roofs on site
- 3) Survey all roofs and include in roofing projects correction of all deficient mechanical and electrical conditions.
- 4) Roofing project specifications should include methods to improve roof run off and drainage, correction or replacement of deficient sheet metal and flashing conditions. Provide rain gutters and downspouts to conduct roof water to site storm drain system.
- 5) Invest in maintenance contract after reroofing projects and initial maintenance repairs.
- 6) We recommend removal of debris from roofs with clearing of all drains twice per year.
- 7) Buildings not listed in Budgetary Estimate matrix below:
 - 508 & 507: Portable classroom buildings with standing seam metal roof. Maintain roofs.
 - 505, 506, 417& 418: Older portable classrooms. Buildings to be replaced with permanent classrooms buildings. maintain roofs as needed until replacement.





		6 E:			-
JDGETARY ESTIMATE:					
AREA	ROOFING	_			
SITE	LA COLINA JHS	<u>_</u>	DATE	1/31/2013	

BUDGETARY ESTIMATE:					
	Sq. Ft. or		Cost Per Sq.		
Building/ Area	unit	ı	ft.	1	· · · · · · · · · · · · · · · · · · ·
500 Building and covered walkways: Roof is 20+ years old, in poor to failing condition, with repair attempts and numerous deficiencies. Some sections of the lower covered walkway roof were found to have a more recent reroofing. This Budget Estimate considers remove and replace all roofs this building.	13,800	х	\$22	=	\$303,600
300, 400, 600 Bldgs. and covered walkways: Majority of roofs are 20+ years old, rated from fair to poor overall condition. Some roofs are more recent. Budget Estimate includes complete removal and replacement. Possible candidate for retrofitting in some areas, which saves costs of removal, disposal and any abatement. Save approx \$6 per square foot. Recommend testing and scanning.	69,000	Х	\$22	II	\$1,518,000
Administration Building including Library, Kitchen and Cafeteria, and upper level Activity room section: Roof approx 20 years old, rated poor to failing condition. Remove roof and replace.	28,970	Х	\$22	=	\$637,340
Allowance for repairs to metal decking, roof drains, downspouts, sheet metal.	1	ea. X	\$20,000	П	\$20,000
Allowance for repairs and correction of improper roof top MEP work and roof penetrations	1	ea. X	\$20,000	II	\$20,000
Maintenance Building: Roof 15+ years old, candidate for retrofitting, Recommend testing and scanning.	2,950	Х	\$16	П	\$47,200
Auditorium Foyer; West main walkway cover. Roofs 15+ years old, rated poor to failing condition. Remove and replace.	2,850	Х	\$22	=	\$62,700
Auditorium main upper roof: 15+ years old, fair condition, Hot B.U.R.; test and scan; Maintain, schedule for restoration 2015.	9,650	х	\$16	=	\$154,400





SITE	LA COLINA JHS			DATE	1/3	1/2013
AREA	ROOFING					
MAINTENANCE REPAI	IRS AND DRAINAGE:					
Electrical & Mechanic	al repairs:					
Allowance for correct mechanical items	ion of deficient electrical conduit and	1	Х	\$25,000	=	\$25,000
Sheet Metal, flashings	s, drainage:					
Allowance for correction of deficient conditions and addition of rain gutters and downspouts		1	Х	\$50,000	II	\$50,000
					1	
SUBTOTAL						\$2,838,240
Escalation, assu	ming 1 year @ 4%					\$113,530
Soft Costs, 30%		•				\$885,531
TOTAL BUDGETARY ESTIMATE						\$3,837,300

Measure Q2010 and Measure R2010 Bond Implementation and Reconciliation Program

LA COLINA JUNIOR HIGH SCHOOL

PROJECT: ROOF REPLACEMENT

BUDGETARY ESTIMATE \$ 3,837,300

STATUS: ASSESSMENT





Varying conditions at the West main walkway cover:

South portion: Cold process B.U.R. with hypalon flashings, in good condition. Damaged North portion (from photo at right) is at top of this picture.

North portion: roof failed, cover board deteriorated and metal decking rusted through. Note transition to different roofing type adjacent to failure.

We recommend full replacement of failed areas. Certain areas on campus may be retrofitted.



Failed roof membrane at Administration Building with repair attempt at roof drain, conduit penetration at left has no roof jack.



Budgetary Estimate includes allowance for correction of improperly installed MEP elements.





Measure Q2010 and Measure R2010 Bond Implementation and Reconciliation Program

LA COLINA JUNIOR HIGH SCHOOL

PROJECT: ROOF REPLACEMENT

BUDGETARY ESTIMATE \$ 3,837,300

STATUS: ASSESSMENT





500 Building:

Main/upper roof portion failed, repair attempts at edge. We recommend removing and replacing entire upper roof.

Covered walkway has some more recently reroofed sections. We recommend evaluating these areas separately to confirm if more economical retrofitting is possible.



Auditorium roof approx. 15 years old, in fair condition. Candidate for testing and retrofitting. Needs maintenance at drains & flashings.



Upper roof section over Activity Room. Example of failed membrane needing replacement.









SITE	LA CUMBRE JUNIOR HIGH	SCHOOL			DATE	1/31/2013
SITE & DISTRICT PERSONN	EL CONSULTED					
Ms. Jo Ann Caines, Pri	Ms. Jo Ann Caines, Principal Tony Perez, Groundskeeper					
Eduardo Mera, Head (Custodian	Gary				
Date last F.I.T. report:	6/10/2009					
Date last Fil. 1. Teport.	F.I.T. Score	96.93%	Rating:	Good		
Issues Identified Deficient:	Window sash failing in ma				nt neeling exter	ior windows
Grounds; asphalt needs re		iiii bullullig classi ooli	is and reen /	gyiii biug, paii	it pecinig exter	or, wiridows.
	,					
REPORTS REVIEWED:	_					
	LEAD PAINT REPORT - Cha ATEMENT CLOSE OUT REPO					ronmental
4/21/2006	ATEMENT CLOSE OUT HET O	Triysical Educati	on ballanig a	na Additoriani	. Criterion Envi	ommericai
				PROJECTED CO	NST .	
MANAGEMENT CODE	PROJI	ECT / AREA		r NOJECTED CC	,51	STATUS
5723	Remaining ADA Lawsuit **	*		\$ 2,6	503 CO	MPLETED
5708	Wireless access **			\$ 210,2	286 CO	MPLETED
02-0000	Undesignated Projects **			\$ 1,4	186 CO	MPLETED
	Site Drainage ***			\$	- CO	MPLETED
5726	Theater / Auditorium Mod	dernization		\$ 2,964,9	24 ASSIGNE	ED FOR DESIGN
5731	Intercom Replacement			\$ 350,3	350 DESIGN	ON HOLD ****
5717	Parking Lot Asphalt			\$ 528,7	710 AS	SESMENT
	Playground Asphalt			\$ 261,4	186 AS	SESMENT
	Window Replacement			\$ 6,189,1	L82 AS	SESMENT
	Exterior Painting & Gutter	S		\$ 904,8	326 AS	SESMENT
	Photovoltaics / Solar, syst	em allowance only		\$ 2,000,0	000 AS	SESMENT
	Lock and Key Upgrade *			\$ 24,0	000 AS	SESMENT
	VOIP Phone System, Infra	structure Allowance		\$ 10,0	000 AS	SESMENT
	Ceiling Replacement			\$ 83,6	518 AS	SESMENT
	Classroom Modernization			\$ 13,703,4	133 AS	SESMENT
	Kitchen Exhaust			\$ 485,0)98 AS	SESMENT
	Multi-Purpose Room Mod	ernization		\$ 984,2	256 AS	SESMENT
	Roof Replacement			\$ 1,461,8	376 AS	SESMENT
	COMPLETED	PROJECTS		\$ 214,3	<u></u> 375	
	PROJECTS IN			\$ 2,964,9		
	ASSESSMENT	PROJECTS		\$ 26,986,8		
	SITE TOTAL			\$ 30,166,1	134	

^{*} Lock and Key Estimates provided by District Facilities and Operations

^{**} Completed Project Expenses posted as of 12/31/12

^{***} Site Drainage work was completed with prior site improvements under Measure V

^{****} Intercom Replacement design on hold pending Beta test of system using VOIP telephone equipment at Dos Pueblos High School





SITE	LA CUMBRE JUNIOR HIGH SCHOOL	DATE	1/3/1/13
AREA	Theater / Auditorium Modernization	BUDGETARY ESTIMATE:	\$ 2,964,924
		BY:	SBSD Fiscal Services + Allowances
DISTRICT OR CONSU	JLTANT DATA AVAILABLE:		
Gary Smith, Theate	r Director		
Monisha Adnina, Pr	oject Architect, PMSM Architects		

INTRODUCTORY COMMENTS:

- 1) Report is general due to project already being assigned for design: PMSM Architects Board vote approval 2/28/12
- 2) Work in Auditorium was completed in 2006 as part of the Campus Modernization Phase II including lighting and electrical system upgrades
- 3) Board has approved design contract with PMSM Architects. Design is in process. Milestones:

2/4/12: PMSM completed drawings to 95% and submitted to SBSD for review

2/15/12: Submitted to DSA for plan review

3) Not included in Estimate provided by PMSM:

Stage curtain and rigging system. Estimate includes some removal and re-setting of stage curtain counterweights. No other costs noted. It is assumed the stage rigging equipment exists and is in working order, no changes other than the counterweights.

Windows at north side of building. Windows are in fair condition due to minimal exposure to direct sunlight. We recommend the windows be inspected for possible inclusion in the WINDOW REPLACEMENT project, and that the replacement (if needed) be completed concurrently with the Theater Modernization.

Roof over the main auditorium area was inspected by TCM and Tremco. We recommend replacing the roof membrane by 2016 - 2018 . There are roof drainage issues.

We recommend roofing and correction of drainage and other issues be completed concurrently with this project. Refer to Roof Report and La Cumbre JHS Roof Replacement report.

RECOMMENDATIONS:

- 1) Proceed with DSA plan review
- 2) Proceed with contractor selection and construction

BUDGETARY ESTIMATE:

ESTIMATED TOTAL PROJECT COSTS per Fiscal Services Project Report through 12/31/12**	\$ 2,470,770
Contingency, 10%	\$ 247,077
Subtotal	\$ 2,717,847
Soft Cost allowance 10% for items not yet posted: Inspection & Testing, etc.	\$ 247,077
TOTAL BUDGETARY ESTIMATE	\$ 2,964,924

^{**} For comparison: Cost Estimate from PMSM Architects / Leland Saylor & Associates 10/31/12 was based on 100% Design Development drawings.

\$ 2,420,123

Measure Q2010 and Measure R2010 Bond Implementation and Reconciliation Program

LA CUMBRE JUNIOR HIGH SCHOOL

PROJECT: THEATER MOIDERNIZATION

BUDGETARY ESTIMATE: \$2,964,924

STATUS: ASSESSMENT, PROJECT IN DESIGN





Existing Stage, proscenium and speaker arrays. Project will provide restoration and upgrading of theater including proscenium, beam restoration, side grilles and shields. Investigation is underway for possible air handling equipment replacement, and additional ductwork. Refer to Attachment "Q-3" for Budgetary Estimate for replacement.



Auditorium view stage. Project includes new flooring, new paneling at side walls and balcony front, fabric-wrapped wall panels, and refurbishing control booth. Project includes a Bid Alternate for re-finishing balcony seating. Flooring replaced



Project will include replacement finishes such as ceilings and walls. Ceiling to have glue-up tile removed, ceiling repaired and painted.





Measure Q2010 and Measure R2010 Bond Implementation and Reconciliation Program

LA CUMBRE JUNIOR HIGH SCHOOL

PROJECT: THEATER MOIDERNIZATION


BUDGETARY ESTIMATE: \$2,964,924

STATUS: ASSESSMENT, PROJECT IN DESIGN



Existing Lighting Control Panel.

Project includes an upgrade to the system



Existing stage rigging shown. Project included removal and resetting of counterweights. Existing rigging system to be utilized.



Project includes lighting and audio equipment replacement. New projector and screen are included



Project does not include windows. We recommend existing windows at North side of theater be inspected and any repairs or replacements be done concurrent with Theater Modernization. Refer to WINDOW REPLACEMENT report.









SITE	LA CUMBRE JHS			DATE	1/31	/2013
ADEA / DDOIECT	INTERCOMA SYSTEMA DEDI A C	CN4CNIT		DUDCETARY ESTIMATE.	ć	250.250
AREA / PROJECT	INTERCOM SYSTEM REPLAC	EIVIENI		BUDGETARY ESTIMATE:		350,350
				BY:		СМ
DISTRICT OR CONSULTAN	T DATA AVAILABLE:					
Bob Nettles, Santa Barba	ra Electrical Design					
INTRODUCTORY COMME						
	ercom system was contracted	to Santa Barl	bara Electrica	l Design. Completion of d	esign and si	ubmittal to
DSA for review and ap	oproval is pending.					
Design is on hold pen	ding Beta test of system using	VOIP telepho	one equipme	nt at Dos Pueblos High Scl	hool	
Budgetary Estimate a	ssumes proceeding with the d	esign and ins	tallation of a	standard new intercom sy	ystem	
RECOMMENDATION:						
	ng at Dos Pueblos High Schoo	1				
complete beta testi	ing at bos i acbios ingli schoo	1•				
DUD 0574 DV 5070 4475						
BUDGETARY ESTIMATE:						
ITEM			Est. Cost			
Engineer's Estimate		\$	225,000	August 2011		
Conduit & hardware - Allo	owance	\$	20,000			
Contingency, 10%		\$	24,500			
SUBTOTAL		\$	269,500			
Soft Costs, 30%		\$	80,850			
TOTAL		\$	350,350			1





SITE	LA CUMBRE JUNIOR HIGH SCHOOL	DATE	1/31/2013
AREA	ASPHALT PARKING LOTS AND PLAYGROUNDS	Main/Front Parking Lot & Parking Lot # 2: South of Main Building	\$528,710
		Playground:	\$261,486
		BY:	TCM

DISTRICT OR CONSULTANT DATA AVAILABLE:

District Facilities PAVING PRIOIRITIES FOR SUMMER 2013 Steve Flowers, Flower Engineering

INTRODUCTORY COMMENTS:

- 1) District Facilities has identified these areas for pavement Summer of 2013. Refer to recommendations below.
- 2) KBZ Architects and Flowers Engineering has completed a design study with design options for the Front/Main Parking Lot. Refer to Asphalt Report
- 3) Fiscal Services reported cost as of YE 2012 \$ 1,074.82. Included in Budgetary Estimate below

RECOMMENDATION:

1) Main/Front Parking Lot:

Steve Flowers reports that a topographical survey and geotechnical report need to be done prior to finishing the design and going to bid. Contract with KBZ Architects & Flowers Engineering, proceed with design and any permit review approvals.

This project may require DSA review due to accessibility elements of the parking lot work changing the present configuration.

We Recommend:

Contract with KBZ Architects & Flowers Engineering, proceed with design and any permit review approvals.

Plan for construction in 2013 if design and approvals can be completed on time. If not, then plan for Summer 2014.

2) Parking Lot # 2: South of Main Building:

This is a pavement restoration and repair project. The existing site configuration will remain the same.

We recommend engaging an engineer to develop a pavement rehabilitation plan and then going to bid and contract for construction in Summer 2013.

3) Playground

This is a pavement restoration and repair project. The existing site configuration will remain the same.

We recommend engaging an engineer to develop a pavement rehabilitation plan and then going to bid and contract for construction in Summer 2013.

Budgetary Estimate on following page





SITE	SITE LA CUMBRE JUNIOR HIGH SCHOOL DATE 1/3			31/2013		
AREA	ASPHALT PARKING LOTS AND PLAYGROUNDS					
DUDGETARY ESTIMATE	S (pending development of engineering and specifications)					
AREA / ITEM	CONDITION; RECOMMENDATION	SQ. FT.	UNIT	EX	TENSION	
Main/Front Parking Lot:	Cracking, weeds, raveling and pot-holing starting; Crack seal, patch, slurry, stripe. Refine and implement design from concept options provided by KBZ / Flowers Engineering	39,600	\$5.00	\$	198,000	
	Allowance for concrete site work, ADA elements, signage			\$	75,000	
Parking Lot # 2: South of Main Building:	Cracking, weeds, weathering, some localized pavement failure; Crack seal, slurry, stripe; Consider adding perimeter transition such as header boards or curbs at fields; Improve inlet surfaces at existing catch basins	29,900	\$3.50	\$	104,650	
Subtotal, Main/front pa	arking lot & Parking Lot # 2: South of Main Building				\$377,650	
Contingency, 10%					\$37,765	
Subtotal					\$415,415	
Soft Costs, 30% of cons	truction cost			\$	113,295	
Total, Parking Lots					\$528,710	
Playground	Cracking, weeds, weathering. Groundskeeper reports severe weed growth; Crack seal, slurry, stripe; Consider adding perimeter transition such as header boards or 0" curbs at fields	59,700	\$3.00	\$	179,100	
Contingency, 10%			1		\$17,910	
Subtotal					\$197,010	
Soft Costs, 30% of cons	truction cost			\$	64,476	
Total, Playground					\$261,486	

LA CUMBRE JUNIOR HIGH SCHOOL

PROJECT: PARKING LOT ASPHALT BUDGETARY ESTIMATE: \$528,710

PLAYGROUND ASPHALT BUDGETARY ESTIMATE: \$261,486

STATUS: ASSESSMENT





Front /Main Parking lot: Cracking raveling, weathering, some pavement failure.

While ADA path of travel issues in the lawsuit were satisfied, safety and accessibility issues remain.

KBZ Architects and Flower Engineering have completed studies with options for improvements

We recommend refinement of design and complete improvements.





Rear/Back Parking lot: Pavement condition similar to Main/Front lot. We recommend Pavement rehabilitation Summer 2013.





LA CUMBRE JUNIOR HIGH SCHOOL

PROJECT: PARKING LOT ASPHALT BUDGETARY ESTIMATE: \$528,710

PLAYGROUND ASPHALT BUDGETARY ESTIMATE: \$261,486

STATUS: ASSESSMENT





Playground area.
Weathering, extensive cracks and weed.
We recommend Pavement Rehabilitation Summer 2013









SITE	LA CUMBRE JUNIOR HIGH SCHOOL		DATE	1/31/2013
	WINDOW REPLACEMENT	_	BUDGETARY ESTIMATE: \$	6,189,182
		BY:	TCM / ARCHITECTURA	AL MILLWORKS
DISTRICT OR	CONSULTANT DATA AVAILABLE:			
Joe Matthey	vs, Architectural Millwork	Alan Fork	oess, Forbess Consulting (Haz Ma	t Consultation)
Joe Wilcox, K	BZ Architects			
Haz Mat Rep	orts: Central Coast Consulting Report 08/09/2000			

INTRODUCTORY COMMENTS:

This Report is based on the Report for Window Replacement for Santa Barbara High School. Windows at both site are similar in their construction, detailing, installation method, and other factors. There are some larger units at the South side of the Theater with arched tops and more detailing. Allowance for these differences is made in the Estimate table below. Refer to the attached visual portion of the Report for specific window styles and counts.

This Report provides a Budgetary Estimate for the complete replacement of the existing wood window units in the Main Building, and the 20's and 30's wings.

Some of the existing wood windows may date back to the original construction while others are from subsequent modernizations. The facilities reported repeated expensive repairs and difficulty in operation.

The wood windows with operable sashes vary in condition from fair to good (North side) to poor to failed at some of the exposed South and West sides of campus. Some of the windows and/ or components of the windows may be salvaged at a cost savings compared with the BUDGETARY ESTIMATE.

Report Assumes:

- 1) Upon completion of a thorough survey of the windows, it may be determined that the project may completed at a lower cost by replacing fewer windows, replacing only certain components of the windows, reusing existing hardware, or other factors
- 2) It is intended that the replacement windows shall retain the original detail and be of wood construction respecting the historical landmark status of the buildings. However, some compromises may be necessary to comply with current codes for energy efficiency and egress.
- 3) This report assumes window units shall be sourced from a single local manufacturer, Architectural Millworks. This firm has proven experience in historical renovation projects in Santa Barbara, as well as providing replacement windows at SBUSD schools.
- 4) Project will require DSA permitting and approval. DSA was consulted by KBZ Architects with regard to permitting requirements. Project will require DSA review and permitting due to the value of project, and energy regulation compliance requirements; Fire Life Safety and accessibility sections will review.
- 5) Work will include testing and abatement of hazardous materials including asbestos and lead
- 6) Architectural Millwork recommends using 1/4" laminated glass to save on maintenance costs versus sealed insulated glass units that fail over time.

Window Blinds:

- 1) Windows have existing venetian-style blinds which are used to regulate natural light and to reduce heat gain.
- 2) Budgetary Estimate includes replacement of existing venetian blinds with new blinds to maintain historical context. New blinds are per specification developed by SBSD Facilities with Jeff Gorell, Levnik & Minor Architects. Pricing provided by Santa Barbara Screen & Shade 37" x 107" units. Recently installed at McKinley ES offices and at SBHS.





SITE	LA CUMBRE JUNIOR HIGH SCHOOL	DATE _	1/31/2013
	WINDOW REPLACEMENT		

RECOMMENDATION:

- 1) Engage Architect and retain window manufacturer to perform a thorough survey and investigation of the windows, to confirm DSA requirements, develop specifications, schematic plans, and schematic estimates.
- 2) Proceed with replacement and/or refurbishment of wood window units. TCM recommends the window replacement be completed with current available Measure Q funds to preserve capital investment, mitigate safety and liability concerns, and to improve the energy efficiency of the building envelope.
- 3) Windows of other structures on campus:

 <u>Locker Room, Cafeteria and MPR are of newer construction than the Main Building. Replacement windows for those structures are included in a separate project report</u>

OPTIONS:

- 1) Phase work to include replacement of those window units with the highest exposure and worst deterioration.
- 2) Alternative Phasing plan:

District may consider as an alternative to coordinate the window replacement with the classroom modernizations so that the windows are replaced sequentially and concurrently with the Classroom Modernizations project.

BUDGETARY ESTIMATE

1) REPLACE existing windows with all new units. Figure is based on Santa Barbara JHS window count at 13.9% fewer than SBHS, all other factors are similar.					\$	4,034,889	
Premium allowance for larger, arched top units at front, upper floor, 4 units x \$5000 ea.							\$ 20,000
2) Removal & Disposal 264 Units x \$200 EACH				\$	52,800		
3) LEAD ABATEMENT	264	Units x	500	EACH		\$	132,000
4) WINDOW BLINDS	210	Units x	\$421	EACH		\$	88,410
			SUBTOTAL				\$ 4,328,099
			Contingend	cy, 10%			\$ 432,810
	TOTAL ESTIMATED WINDOWS, ABATEMENT, AND INSTALLATION				LATION	\$ 4,760,909	
			SOFT COSTS, 30%				\$ 1,428,273
	TOTAL ESTIMATED					\$ 6,189,182	

LA CUMBRE JUNIOR HIGH SCHOOL

PROJECT: WINDOW REPLACEMENT

BUDGETARY ESTIMATE: \$6,189,182

STATUS: ASSESSMENT



Window replacement is similar to the considerations for Santa Barbara High School and Santa Barbara Junior High school. This site does have some unique units with greater detailing, such as this 14' high arched unit at side of Theater.





Windows on all three sites have severe deterioration and require multiple repairs, especially on the South and West sides of buildings. This is classroom 106 with western exposure.



Deterioration and wear of units varies on site depending on the exposure.

Left, severe deterioration at South side of building; Right, units at the North side in fair condition.

We recommend a thorough survey to determine if any units may be retained





LA CUMBRE JUNIOR HIGH SCHOOL

PROJECT: WINDOW REPLACEMENT

BUDGETARY ESTIMATE: \$6,189,182

STATUS: ASSESSMENT



Height of work is a factor in cost of this project.

Replacement units will retain architectural elements such as turned detailed post.



Industrial Arts rooms, south facing exposure. Lower operable units have been replaced with solid wood panels due to damage from athletic equipment, balls, etc.

Windows were counted and classified by type. Refer to the Window Study on the following pages.

Budgetary Estimate for replacement units was provided by Architectural Millworks, Santa Barbara.

We recommend SBUSD to engage architect and retain window manufacturer to perform a thorough survey and investigation of the windows, to confirm DSA requirements, develop specifications, schematic plans and schematic estimates.

Assessment process is similar for Santa Barbara Junior High School and La Cumbre Junior High school.

Refer to specific Reports for those sites

Deterioration and wear of units varies on site depending on exposure.

Left, server deterioration at south side of building; Right, units at north side in fair condition.


We recommend a thorough survey to determine if any units may be retained





Type 1
ARCHED TOP
2' 6"w x 6' h
SINGLE HUNG

Type 1A similar, 2' 4"w x 8' h SINGLE HUNG



Type 1B
3' w x 9' h
Fixed arch over
two awnings
(Sim. Type 7 @ SBJHS)








TYPE 4B 3'W x 9' H All awnings

Type 4C 2'-9"' W X 9' H All awnings

Type 4D 3'-9"' W X 6' H All awnings







TYPE 5 double shown Type 5 Triple is similar

All units are 9' high


All Awnings

Posts between window units 3-1/2" D

detailing is simple, like maybe 1" half-round vertical at the sides of post







TYPE 6 Quad shown —6 Double & 6 Triple are similar

All units are 9' tall

All Awnings

Posts between window 4-3/4" wide.

Looks like the turnings are attached to the face of posts (as opposed to being a part of the posts themselves)

(Similar to Santa Barbara high school)







TYPE 8 3' x 4' SINGLE HUNG

Type 8A 3'6" x 5'. Single Hung


Type 8B 3' x 3' Full Bound

Type 8C 3'6" x 5' Fixed sash, wire glass





TYPE 9 2'6" x 10'
Arch top over
two awnings










TYPE 11 5' x 10' Fixed unit over out-swinging patio doors



TYPE 12 6' x 16'
Fixed arched unit
over
side – by – side
3-high awning
units with turned
post







TYPE A door unit
3' x 7' door with 1'9" wide
fixed side panel
Fixed window unit above:
4'9" x 5' high









SITE	LA CUMBRE JUNIOR HIGH SCHOOL	DATE	1/31/2013
AREA	EXTERIOR PAINT & GUTTERS		
		BUDGETARY ESTIMATE: \$	904,826
DISTRICT OR CONSUL	TANT DATA AVAILABLE:	BY:	TCM

Mr. Mera, Head Custodian Tony Ortiz, Groundskeeper

Haz Mats: CCC Report 11/9/2001 identified:

ACM: Detected in window putties, and trace amounts in exterior plaster. We recommend additional sampling to determine the extent

Lead-based paint may be assumed in window paint and other exterior trim due to the age. We recommend additional sampling, and abatement as part of this project.

INTRODUCTORY COMMENTS:

Report includes the general condition of the external surface finishes on the elements listed below. Functional issues are noted where appropriate.

Report considers the Main Building, SBCA & Library wing (116-120), MPR, 300 building (Physical Education and Industrial Arts, Field Restroom Building and SBCA portables).

District may elect to remove MPR from this project and defer the exterior painting to the MPR Modernization project.

Exterior Building surfaces: walls, ceilings, soffits, adjoining elements.

Main Building

Walls:

Walls appear to be concrete with stucco skim coat as finish.

Concrete appears to be sound. Some minor superficial repairs may be required.

Stucco finish skim coat is chipping, flaking, peeling, and/or sloughing in some areas. In these cases, removal of the damage to competent limits and substrate required. Patching of stucco skim coat to match existing adjacent surfaces required.

Conditions vary based on the direction of the surface. The North is in better condition than the South, West, and East sides due to less severe exposure conditions.

Window sills (painted red) constructed of the same materials exhibit the same characteristics, requires

similar repair and treatment.

Ceilings, Exterior

Ceilings at Main Building and at SBCA (single-story south wing) have similar, yet less severe conditions

than the walls.

Doors, Windows and Frames

WINDOWS

Wood window are addressed in WINDOW REPLACEMENT, see separate report sheet

Windows on Multi-Purpose Room addressed under MPR MODERNIZATION, see separate report sheet

Windows on SBCA rooms are in two categories:

1. Full-bound single lite glass, either fixed panes or louvered operation. These are generally in fair to good, serviceable condition.

Recommend these be evaluated and maintained with the maintenance budget.

 ${\bf 2}$. Fixed sash windows at SBCA Office are in fair - good serviceable condition. Recommend these be repaired and repainted

DOORS

Exterior doors were generally in fair to good, serviceable condition.

Recommend opening operation be evaluated individually and included in a scope for the exterior

painting.. Those requiring replacement may be included in the Windows project.





SITE	LA CUMBRE JUNIOR HIGH SCHOOL	DATE	1/31/2013
AREA	EXTERIOR PAINT & GUTTERS		

Sunshade / Security Louvers

Installed on the single-story portion of the SBCA: Rooms 115 - 118, and Library Grounds keeper reports sunshade / security louvers function and are mostly trouble-free. Recommend removal, painting and replacement of these shades be included in painting scope of work so that painter can access the walls and window frames behind the shades.

Walkway Canopies and their Supporting Elements

Walkway structure (from Main Bldg to SBCA) is cement plaster over framing, in good condition. Scope of work to include power washing, minor repair and painting.

Ornamental Ironwork: Stairs and Ramp Railings, Handrails, Balcony Railings, Fences, Gates and Enclosures

Appear to be in fair to good condition. Much is new. All areas should be evaluated and necessary repairs done by District, or included in scope of work.

Scope of work to include preparation and painting.

Fences are either galvanized material or are factory-coated. No work required.

GUTTERS & DRAINS

Consulted with groundskeeper, Tony. Some issues are obvious, but he stated there are many leaks and damage that can not be seen without water test.

Sheet metal flow area around the tower/cupola at the North side over the main entrance needs to have the bird droppings and debris regularly cleaned from around the perimeter.

BUDGETARY ESTIMATE (Pending development final scope of work and specifications)

<u> </u>	, ,	
Building/ Area	Comments	
Main Building, SBCA & Library wing (116-120), MPR, 300 building (Physical Education and Industrial Arts.	MPR expense may be deleted from this report and moved to MPR MODERNIZATION if it is decided to complete the workwith that project	\$ 600,000
Field Restroom Building & SBCA portables		\$ 7,500
Rain gutter and downspout repair allowance		\$ 10,000
Subtotal		\$ 607,500
Contingency, 10%		\$ 61,750.00
Escalation, assuming 1 year @ 4%		\$ 26,770.00
SOFT COSTS 30%		\$ 208,806
	TOTAL	\$ 904,826





SITE	LA CUMBRE JUNIOR HIGH SCHOOL	DATE _	1/31/2013
		_	
AREA	CEILING REPLACEMENT	BUDGETARY ESTIMATE:	\$ 83,618
		BY:	TCM

DISTRICT OR CONSULTANT DATA AVAILABLE:

Haz Mats: CCC Report 11/9/2001 identified no Asbestos-Containing materials or Lead-Containing Materials in the ceiling tiles

INTRODUCTORY COMMENTS:

This report includes the Cafeteria and the Hallways in the Main Building. The ceilings throughout these spaces and in most of the classrooms are 2' x 2' slotted ceiling tiles.

Report assumes the ceilings in the classrooms and other spaces will be replaced with the CLASSROOM MODERNIZATION project.

District personnel consulted indicated this project was listed as a Measure Q project for aesthetic purposes. While the ceiling tiles are older, and replacement tiles are not available, the tiles themselves are performing their function.

Budgetary Estimate assumes existing suspension grid system is sufficient and may be reused. Replacement of the suspension grid is not included in the Budgetary Estimate.

Lighting throughout is T-8 fluorescent fixtures with electronic ballasts. Steve Vizzolini indicated this meets current District objectives and that the fixtures do not need to be replaced.

RECOMMENDATIONS

Replace ceiling tiles as an aesthetic measure.

Include cost of upgrading lighting to energy efficient LED or other lighting and concealment of recently completed technology and low voltage systems components where applicable.

BUDGETARY ESTIMATE:	Sq. Ft. or unit		Cost Per Sq. ft. or unit		Total
Demo / remove existing ceiling tiles	16,250	Χ	\$0.25		\$ 4,063
Replace ceiling tiles, hallways, Main Building	16,250	Х	\$2.00	=	\$ 32,500
New Acoustical ceilings, Cafeteria	3000	Χ	\$2.50	=	\$ 7,500
Allowance, manipulation of light fixtures and other elements	1	Х	\$10,000.00	=	\$ 10,000
Contingency, 10%					\$ 5,406
Escalation, 4% x 24 months					\$ 4,853
Subtotal					\$ 64,322
Soft Costs, 30% of Estimated Construction	Cost				\$ 19,297
	TOTAL BUDGE	TARY EST	IMATE	•	\$ 83,618

LA CUMBRE JUNIOR HIGH SCHOOL

PROJECT: CEILING REPLACEMENT

BUDGETARY ESTIMATE: \$83,618

STATUS: ASSESSMENT






Typical suspended grid ceilings in Main Building Hallways and Cafeteria. Budgetary Estimate assumes existing suspension grid will be utilized.

District Electro-Mechanical Forman Steve Vizzolini advised that the existing light fixtures are T-8 fixtures with electronic ballasts. These fixtures meet District energy efficiency standards and do not need to be replaced.







We recommend ceilings in classrooms and other spaces to be replaced with the CLASSROOM MODERNIZATION project









SITE	LA CUMBRE JUNIOR HIGH SCHOOL	DATE	1/31/2013	
AREA	CLASSROOM MODERNIZATION	BUDGETARY ESTIMATE:	\$13,703,433	
		BY:	TCM	

DISTRICT OR CONSULTANT DATA AVAILABLE:

Classroom tour with Principal Mrs. Caines

Haz Mats: CCC Report 11/9/2001 identified:

ACM identified in flooring, baseboards and limited other materials.

Lead content identified in various surfaces and materials.

Scope of project to include abatement of lead at disturbed or impacted areas

INTRODUCTORY COMMENTS:

Project includes a general modernization of forty-one rooms listed below, not including portable classroom buildings.

Sample classrooms inspected: 103 & 109. Mrs. Caines demonstrated 103 and discussed deficiencies and desired upgrades Noted:

Flooring: ACM in floor tile and base per report

Generally outdated with original-style wood trim and cabinetry. Some had black boards

Ceilings are slotted 2'x 2' tile type present throughout the campus

Doors have been retrofitted with new door hardware.

Door frames (to hallways) include transom window openings which are either covered over with painted paneling or they contain louvers. Louvers assumed to assist in ventilation.

Windows are wood sash awning type. Refer to separate report on wood windows

Technology needs to be addressed (Plasma screens, smart classroom technology)

Heating, Ventilation and Air Conditioning:

Heating: radiators connected to central steam or boiler system.

Ventilation: Windows with venetian blinds

Air Conditioning: None present in rooms reviewed. (A/C was present in computer labs rms. 122 & 123)

Electrical and Lighting:

Power: Generally insufficient. Some areas adapted with additional surface-mounted conduits and outlets.

Lighting: Task lighting needs upgrading to modern energy compliant fixtures.

Classrooms are outfitted with current Fire Alarms and Wireless internet

Rooms mostly equipped with TV's and VCR or DVD players. A few had newer plasma screens

Interim Housing:

Budgetary Estimate includes allowance for 14 leased classroom units for two years, set up on a paved asphalt space on campus. Assumes Modernizations should be completed over two semesters and a summer period, with allowance of one month each for mobilization and demobilization. No interim leasing facilities included for 301-306.

RECOMMENDATIONS:

- 1) Implement design and programming study with architect and site. Develop budget figures and schedule for completion.
- 2) Develop multi-year plan for phasing, including interim housing.
- 3) Window Replacements may be included in the MODERNIZATION of individual classrooms so as to avoid having to take individual rooms out of service for a separate window replacement project.





SITE	LA CUMBRE JUNIOR HIGH SCHOOL	DATE	1/31/2013
AREA	CLASSROOM MODERNIZATION	_	

- 4) Roof repairs and mechanical replacements should be scheduled in connection with specific areas, as those areas are scheduled for modernization
- 5) Two portable buildings on site (used by SBCA) appear newer and have foundations and accessibility installed within the past five years. Recommend that these be retained in service for at least ten years. Refer to Portable Classroom Report.

NOT INCLUDED in this Estimate:

- 1) Portable classroom buildings in use by SBCA.
- 2) Rooms in the single-story wing used by SBCA: 116-118 and Library
- 2) MPR: covered in the separate reports for MPR Modernization.

BUDGETARY ESTIMATE:

Modernization of classrooms in	existing build	lings::				•
<u>Building</u>	Qty. of roor	<u>ns</u>				
Main Bldg	33		oms in the Main partment) at We		_	
300 Building	6	PE & Indu	strial Arts Buildir	ng		
			Amount		F	Rooms
			Per Room			Total
SUBTOTAL	39	X	\$117,332	=	4	4,575,948
Ancillary and support spaces	3,744	Х	\$122	=		456,768
Contingency 10%						503,272
Escalation, 24 Months avera	age @ 4% / y	ear				451,737
Subtotal					į	5,987,724
Soft Costs, 30% of construct	ion cost				\$ 1	1,372,784
Interim Housing, rental classroo	ms **					
11 units x 20 months rental	220	Х	\$800	=	\$	176,000
Set up, delivery, tear down and return	11	Х	\$1,200	=		13,200
Site prep, set up, demobilization	n				\$	100,000
Moving & Storage Expense:	33	Χ	2,000	=	\$	66,000
TOTAL BUDGETARY ESTIMA	TE			\$	13	3,703,433

^{**} Exact Interim Housing Plan and rental building locations will be determined jointly with La Cumbre JHS and Facilities Staff.

Ancillary and support spaces tabulation:

			_
Classrooms	39	Х	960 average s.f.
		=	37,440.00 SF of classrooms
		X 10% =	3,744 SF of ancillary & support space

LA CUMBRE JUNIOR HIGH SCHOOL

PROJECT: CLASSROOM MODERNIZATION

BUDGETARY ESTIMATE: \$13,703,433

STATUS: ASSESSMENT





Classroom modernization will include upgrade to energy efficient fixtures, all new ceilings and finishes, new ceilings, removal of old flooring containing asbestos, replacement of aged cabinetry and technology for uniformity with District Standards.



Mrs. Caines reported rooms have generally inadequate power to meet current classroom requirements for equipment and computers. Some outlets have been added over the years.

Modernization will upgrade electrical power and data systems.



Pictured: failed and repaired window at room 106, south facing side of building. Window replacement costs and recommendations are included in the WINDOW REPLACEMENT report.





LA CUMBRE JUNIOR HIGH SCHOOL

PROJECT: CLASSROOM MODERNIZATION

BUDGETARY ESTIMATE: \$13,705,433

STATUS: ASSESSMENT





Physical Education (left) and Industrial Arts(right) in 300 building received modernization in approximately 2007. For budgetary coverage purposes the Estimate includes full modernization of these rooms.









SITE	LA CUMBRE JUNIOR HIGH SCHOOL	DATE	1/31/2013
AREA	KITCHEN EXHAUST		
		BUDGETARY ESTIMATE: _\$	485,098
		BY:	TCM

DISTRICT OR CONSULTANT DATA AVAILABLE:

Hugh Mc Ternan, AE Mechanical Group Engineers Steve Vizzolini, SBSD Electro-Mechanical Supervisor

Haz Mats: CCC Report 11/9/2001. Report pre-dates the Boiler Replacement which affected materials in the boiler room and mechanical systems. We recommend sampling of affected areas.

Lead: We recommend sampling of affected areas.

INTRODUCTORY COMMENTS:

Report includes replacement of the existing Kitchen Exhaust blower unit, replacement of kitchen vent hood and modification of, and addition to the existing ductwork, and cost for incidental building work due to equipment and duct installation. Inspected system with Hugh McTernan, AE Mechanical Group Engineers. AE Mechanical designed the replacement central heating system boiler and they are familiar with the campus.

System is out of code due to vent hood and general space exhaust on the same blower unit. Blower unit itself is approx. 40 years old, and functioning.

Cafeteria and Kitchen located in lower level of building at South end of main building. Approx 5' below exterior grade level. Space is contiguous with the service and food preparation areas.

Space heating for the student dining area provided by fan coil units in the closets at the East and West side of space, connected to main hydronic boiler system. Hydronic boiler system was install in 2008 with Measure V funding. Ventilation is provided via operable windows and doors. Separate make up air facilities are in place for food service equipment.

RECOMMENDATIONS:

Engage Mechanical Engineer to complete design and obtain schematic estimate.

Proceed with construction and replacement of system. Schedule for Summer 2014.

BUDGETARY ESTIMATE (Pending development final scope of work and specifications)

Building/ Area	Comments		Budgetary Estimate	
Demolition and abatement	Removal of equipment and existing ducting; Perform sampling for asbestos and lead containing materials	\$	20,000	
Equipment, ductwork and installation		\$	200,000	
Building construction - Exhaust duct chase through roof and related work		\$	100,000	
Contingency 10%		\$	25,000	
Escalation, 24 Months average @ 4% / year	•	\$	28,152	
Subtotal		\$	373,152	
SOFT COSTS 30%		\$	111,946	
	BUDGETARY ESTIMATE TOTAL	\$	485,098	

LA CUMBRE JUNIOR HIGH SCHOOL

PROJECT: KITCHEN EXHAUST SYSTEM

BUDGETARY ESTIMATE: \$485,098


STATUS: ASSESSMENT





Existing Blower fan in basement Boiler Room area is 40+ years old. Fan and duct system serves kitchen, cafeteria and support spaces. System is not in compliance with code. Project will include removal of this unit and duct and replacement with new blower, controls and ductwork.







Exhaust vent at top above sink does not extend into and exhaust all areas of the kitchen and cafeteria.

Project will include new ductwork compliant with code to provide necessary exhaust ventilation to all areas.









SHE	LA CUMBRE JUNIOR HIGH SCHOOL	DATE	1/31/2013	
AREA	MULTI-PURPOSE ROOM			
		BUDGETARY ESTIMATE:	\$984,256	
DISTRICT OR CONSULTANT DATA AVAILABLE:		BY:	TCM	

Haz Mats: CCC Report 11/9/2001 identified:

ACM identified. Limited to vibration cloth on insulation of mechanical equipment

Lead: Confirm that tile identified in CCC report has been removed with the ADA improvements.

INTRODUCTORY COMMENTS:

ADA accessibility facilities appear to have been installed with lawsuit improvements

Structure: Appears sound, code compliant. Consult with Architect to determine if structural upgrades required.

Flooring may be original. Not identified as ACM in Report. Sampling recommended.

Ceilings: open structure in main rooms with some insulation / padding present

Doors have been retrofitted with new door hardware. Door and frames are standard and appear functional.

Windows are single strength and do not appear to be dual-paned or energy efficient

Technology: Did not notice any Technology elements present

Equipment:

Basketball backboards, gymnastic rings

Partition is dated, appears to have function issues.

Heating, Ventilation and Air Conditioning: present . Appears to be older units.

Plumbing: Restrooms and drinking fountains newer, ADA compliant

Electrical and Lighting:

Power: Generally insufficient. Some areas adapted with additional surface-mounted conduits and outlets.

Lighting:

Task lighting needs upgrading to modern energy compliant fixtures.

Low Voltage systems: Present, sufficient

RECOMMENDATION:

Although the MPR has some finishes and fixtures it is serviceable and is not used as a lunch room. It therefore has less wear and tear than MPR's on some other campuses such as Santa Barbara Junior High school. ADA compliant upgrades are completed. It is our opinion the modernization of this building may be deferred until funding is available.

Roof should be replaced as a priority project. Budgetary Estimate included in ROOF REPLACEMENT project

BUDGETARY ESTIMATE:

Construction hard costs, budget \$150 per sq. ft. x 4,500 sq. ft. bldg.	\$ 675,000
Contingency 10%	\$ 25,000
Escalation, 24 Months average @ 4% / year	\$ 57,120
Subtotal	\$ 757,120
SOFT COSTS 30%	\$ 227,136
Interim facilities, allowance	\$ 50,000

TOTAL BUDGETARY ESTIMATE \$984,256

LA CUMBRE JUNIOR HIGH SCHOOL

PROJECT: MPR MODERNIZATION

BUDGETARY ESTIMATE: \$984,256

STATUS: ASSESSMENT



MPR exterior. Accessibility and door hardware issues have been completed with ADA compliance project







Accessible restrooms and drinking fountains are completed.





Modernization will consist of a general aesthetic and functional upgrade of the building with new finishes for the floors, walls, ceilings, new energy efficient lighting fixtures,









SITE	LA CUMBRE JHS	DATE	1/31/2013	
AREA	ROOF REPLACEMENT	BUDGETARY ESTIMATE:	\$1,461,876	
		BY:	TCM	

DISTRICT OR CONSULTANT DATA AVAILABLE:

Channel Coast Corporation Asbestos Report 9/11/2001
Inspection of all roof surfaces with Jim Gilday and Joe Razo, Tremco Roofing Products
Mike Parrent, Channel Islands Roofing Company
Mr. Mera, Head Custodian

INTRODUCTORY COMMENTS:

All roofs on site were inspected by TCM together with Jim Gilday, Technical Services Representative, Tremco Roofing. Mr. Gilday has knowledge of the roofing projects at the site. Refer to Roof Diagram and Roofing Report.

RECOMMENDATIONS:

- 1) Evaluated existing roofs on Main Building, MPR, SBCA wing, 300 Building for possible restoration or retrofitting. Save cost on roof removal and asbestos abatement. Refer to Roofing Report
- 2) A regular scheduled evaluation and maintenance program must be utilized to protect the capital asset investment of the roof itself and to protect the building.
- 3) Roofing for MPR should be done with the MPR MODERNIZATION project.
- 4) Various issues identified on the two-piece clay tile roofs. These roofs should be evaluated and repaired. Unit prices may be used where quantity and scope can be evaluated and authorized on site.
- 5) Theater Wing: Replace the roof on the main auditorium area concurrent with the Theater Modernization. Correct clay tile, drainage, and other issues. Refer to Roofing Report.
- 6) All rain gutters and downspouts should be inspected, repaired and corrected prior to the Exterior Painting Project.
- 8) Install red cap sheet surfaces over the clay tiles at the roof access points. This provides a non-slip walking surface and prevents damage to tiles.

Budgetary Estimate on following page





SHE	LA CUMBRE JHS				DATE	1/3	1/2013
AREA	ROOF REPLACEMENT						
BUDGETARY ESTIMA	TF·						
5050217411 20111717		Sq. Ft. or			Cost Per Sq.		
	Building/ Area	unit			ft.		
Clay tile roofs, variou	us areas:						
Inspect and develop	scope for repair and correction of	1	ea.	Χ	\$20,000	=	\$20,000
deficient issues. Refe	er to Roofing Report.						
121 / 122 Flat Tile Ro	oof:						
Misc. repairs, refer to	o Roof Report. Replace damaged	1	ea.	Χ	\$5,000	=	\$5,000
fascias and sheet me							
Option: Consid Refer to Roof R	er removing clay tile roof, replace with n Report	netal roof a	nd pho	otov	oltaic panels.		
Hot B.U.R. areas : M	ain Building flat roof area , Theater rear,	/west, Thea	ter				
lower/south: Retrofi	t over existing hot gravel roof no later th	an 2016.					
1) Correct woo	d fascia, edge blocking, sheet metal,				4		4
	downspout issues. Budget Allowance	1	ea.	Х	\$5,000	=	\$5,000
2) Replace roof	no later than 2018. Scan and test for						
possible retrofi		19,438	Х		\$18.00	=	\$349,884
Modified Bitumen Ro	oof areas: Theater main roof & entry por	tico, east to	wer fl	at			
roof, east ramp roofs	s # 1&2, & covered walkway:						
1) Clean roofs a	and clear drains immediately before	1	ea.	Y	\$2,500	=	\$2,500
rainy season. B	udget Allowance		ca.		72,300		72,500
	f no later than 2016. Scan and test for	6200	Х		\$18.00	=	\$111,600
retrofitting.		0200			Ψ10.00		Ψ111,000
	<u>2-120:</u> Severe damage to perimeter shee	et metal. Ro	of nea	ır			
end of service life.							
1) Replace roof	f as soon as possible. Scan and test for	28445	Х		\$16.00	=	\$455,120
	hts, sheet metal, and correct deficient	1	ea.	Х	\$10,000	=	\$10,000
MEP installatio	ns and penetrations. Budget Allowance				, -,		, ,,,,,,
Multi-Purpose Buildi	ng:						
Remove and replace	roof. Redesign perimeter detailing,	4500	Х		\$22		\$99,000
add rain gutters and	downspouts.	4300	^		ΨZZ		755,000
300 Bldg, Industrial A	Arts/ PE: Roof under warranty until 2015	. Maintenar	nce On	ly.			\$0
SUBTOTAL							\$1,058,104
Escalation, assuming	; 1 year @ 4%						\$86,341
Soft Costs, 30%	of construction cost						\$317,431
TOTAL BUDGET	TARY ESTIMATE			_			\$1,461,876

LA CUMBRE JUNIOR HIGH SCHOOL

PROJECT: ROOF REPLACEMENT

BUDGETARY ESTIMATE: \$1,461,876

STATUS: ASSESSMENT





<u>Auditorium Main Roof: Modified Bitumen membrane 15-20 years old.</u>
We recommend replacement of this roof concurrent with THEATER MOSERNIZATION project.

Left: Modified Bitumen roof 20+ years old. We recommend test and scan for retrofitting, replace with new drain and overflow in drain sump. Note ponding stain.



Right: Repair attempts at vent units over stage. We recommend scope of repairs be developed and completed with the re-roofing.



Main Building upper roof: Built-up gravel roof Modified Bitumen membrane 15+ years old. We recommend test and scan for retrofitting by 2016. Identify and correct deficient conditions

03.28.2012

Left: No gutter and downspout from roof above – water shedding to lower roof degrading plaster wall; deteriorated attic access doors & frames

Right: Roof membrane was rated fair to poor condition. Wind scar, degradation of asphalt membrane:





LA CUMBRE JUNIOR HIGH SCHOOL

PROJECT: ROOF REPLACEMENT

BUDGETARY ESTIMATE: \$ 1,461,876

STATUS: ASSESSMENT





SBCA wing (116-120 + Library). Roof rated Poor Overall Condition, 15+ years old. Multiple issues, we recommend test and scan for possible retrofitting, and re-roofing as soon as possible.

Left: Wind scar on edge of roof at leading edge of prevailing wind, exposed and degraded bitumen with moss growth .

Right: Failure of joint in sheet metal. Water intrusion degrading plaster building finish, possibly roof framing..



MPR Roof. We recommend complete re-roofing with MPR MODERNIZATION



Covered walkway roof was rated poor to fair condition. We recommend replace as soon as possible, and install gutters and downspouts to divert rain water from area at entry to SBCA office entry





LA CUMBRE JUNIOR HIGH SCHOOL

PROJECT: ROOF REPLACEMENT

BUDGETARY ESTIMATE: \$1,461,876

STATUS: ASSESSMENT





Budgetary Estimate includes allowance for correcting issues with clay tile roofs, rain gutters & downspouts, sheet metal, and more

Example: Wood blocking and new metal edging over edge of building; Rework lower perimeter guttering and metal edge termination under tile; Correct downspout and gutters. Add down drain pans at bottom of downspouts discharging to this roof.

Example: Rework tile mansard valleys to eliminate heavy debris build-up. Remove debris clogging valleys.





Debris should be cleared from drains and run off areas annually before rainy season



